

Profile/Ph	oto Observatior	n Report				RedZone
Date: Pipe Length (ft P.O.#: Customer:	04/14/2018): 151.6	Weather: Owner: Surveyor: Clean Date:	NA Jen Costello 01/01/1900	Codir Pre C PSR: Shap	Clean: No P-5	CP 6.0 Pre-Cleaning 505-081-082
Street:	FOXCROFT STREET		Flow Control:	Not C	Controlled	
City:	Hobart, IN		Year Renewed:			
Location:	Yard		Tape/Media #:			
Purpose:	Routine Assessme	nt	Dia/Height:	10"		
Use:	Sanitary		Material:	VCP		
Drain Area:	NA		Lining:			
Category:	NA					
Comment:	Flow direction is n	narked wrong.				
Location Detai	ls:		Direction of Sur	vey: Dowr	nstream	
US MH:	M-505-082	DS MH:	M-505-081	Total Length Sur	rveyed (ft):	20.9
O&M Index:	0.00	O&M Quick:	000	00 O&M Ra	ating:	0.00
Structural Index:	0.00	Structural Qu	uick: 000	00 Structur	al Rating:	0.00
Overall Index:	0.00	Overall Quic	k: 000	00 Overall I	Rating:	0.00






Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-505-082




Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	30.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	3.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	TF
Description:	Tap Factory

Distance (ft):	5.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	MSA
Description:	Abandoned Survey

Distance (ft):	20.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	high water