


Profile/Pho	oto Observation I	Report				RedZone
Date: Pipe Length (ft) P.O.#: Customer:	04/14/2018 : 299.7	Weather: Owner: Surveyor: Clean Date:	NA Jen Coste 01/01/19	-	Coding: Pre Clean: PSR: Shape:	PACP 6.0 No Pre-Cleaning P-505-084-085 C
Street:	FOXCROFT STREET		Flow Contro	ol:	Not Controlled	
City:	Hobart, IN		Year Renew	ved:		
Location:	Yard		Tape/Medi	a #:		
Purpose:	Routine Assessment	:	Dia/Height:	:	10"	
Use:	Sanitary		Material:		VCP	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Details	s:		Direction o	f Survey:	Upstream	
US MH:	M-505-084	DS MH:	M-505-085		Total Length Surveyed (ft):	58.8
D&M Index:	0.00	O&M Quick:		0000	O&M Rating:	0.00
Structural Index:	0.00		uick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick	<:	0000	Overall Rating:	0.00






Code: Description:	AMH Manhole
	_
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-505-085



Code: MWL Description: Water Level


Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	20.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	TFA
Description:	<b>Tap Factory Active</b>
Distance (ft):	9.0
Distance (ft):	9.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	


Remarks:

## Tuesday, December 8, 2020



Code:TFADescription:Tap Factory Active

Distance (ft):	20.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	MSA
Description:	Abandoned Survey

Distance (ft):	58.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	debris under water