
Profile/Photo Observation Report



| | | • | | | ROBOTICS | |
|-------------------|-----------------------|---------------------|----------------------|-------------------------|-------------------|--|
| Date: | 01/21/2022 | Weather: | | Coding: | PACP 7.0 | |
| Pipe Length (ft): | 201.2 | Owner: | City of Hobart | Pre Clean: | Heavy Cleaning | |
| P.O.#: | YES502259 | Surveyor: | S. Bucklin | PSR: | P-506-011-010 | |
| Customer: | City of Hobart | Clean Date: | 01/17/2022 | Shape: | С | |
| Street: | South Colorado Street | | Flow Control: | Not Controlle | Not Controlled | |
| City: | Hobart, IN | | Year Renewed: | | | |
| Location: | Local rural streets v | with light traffic, | , t Tape/Media #: | | | |
| Purpose: | Routine Assessmen | nt | Dia/Height: | 12" | | |
| Use: | Sanitary Sewage Pi | pe | Material: | VCP | | |
| Drain Area: | | | Lining: | None | | |
| Category: | NA | | | | | |
| Comment: | | | | | | |
| Location Details: | | | Direction of Survey: | Downstream | | |
| US MH: M | -506-010 | DS MH: | M-506-011 | Total Length Surveyed (| ft): 201.2 | |

| O&M Index: | 2.03 | O&M Quick: | 412K | O&M Rating: | 132.00 |
|-------------------|------|-------------------|------|--------------------|--------|
| Structural Index: | 2.67 | Structural Quick: | 4232 | Structural Rating: | 24.00 |
| Overall Index: | 2.11 | Overall Quick: | 4332 | Overall Rating: | 156.00 |
| _ | | | | _ | |

| | Position | Code | Observation | Video (sec) | Grade |
|------------------|-----------|-----------|---------------------------------|-------------|-------|
| M-50 | 06-010 | | | | |
| | 0. | АМН | Manhole | 1 | NA |
| - 1 | 0. | MWL | Miscellaneous Water Level | 71 | NA |
| | .3 | DSF(S01) | Deposits Settled Fine | 92 | M 2 |
| | 6.9 | JAM | Joint Angular Medium | 125 | S 3 |
| | 22.9 | IWJ | Infiltration Weeper Joint | 239 | M 2 |
| | 22.9 | DAE | Deposits Attached Encrustation | 248 | M 2 |
| | 85.5 | MWLS | Miscellaneous Water Level Sag | 473 | S 2 |
| -1 | 94.7 | DAE | Deposits Attached Encrustation | 519 | M 2 |
| -1 | 98.6 | DAE | Deposits Attached Encrustation | 557 | M 2 |
| | 102.6 | DAE(S02) | Deposits Attached Encrustation | 610 | M 2 |
| Camera Direction | 1///123.7 | TF | Tap Factory | 702 | NA |
| | 141.4 | TF | Tap Factory | 817 | NA |
| | 159.6 | MWLS(S03) | Miscellaneous Water Level Sag | 899 | S 2 |
| | 181.0 | MWLS(F03) | Miscellaneous Water Level Sag | 983 | S 2 |
| | 186.3 | MWLS(S04) | Miscellaneous Water Level Sag | 1011 | S 4 |
| | 189.8 | JOM | Joint Offset Medium | 1038 | S 3 |
| | 192.3 | MCU(S05) | Miscellaneous Camera Underwater | 1074 | M 4 |
| | 196.4 | MCU(F05) | Miscellaneous Camera Underwater | 1123 | M 4 |
| | 197.6 | MWLS(F04) | Miscellaneous Water Level Sag | 1144 | S 4 |
| | 200.2 | DSF(F01) | Deposits Settled Fine | 1164 | M 2 |
| | 200.2 | DAE(F02) | Deposits Attached Encrustation | 1172 | M 2 |
| | 201.2 | AMH | Manhole | 1248 | NA |



| Code: | АМН |
|---------------------|-----------|
| Description: | Manhole |
| | |
| Distance (ft): | .0 |
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | |
| Clock To: | |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Continuous Index: | |
| Within 8" of Joint: | NO |
| Remarks: | M-506-010 |
| | |



Code: MWL

Description: Miscellaneous Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO



Code: **DSF**

Description: Deposits Settled Fine


Distance (ft): .3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 5
Clock To: 7
1st Value:

2nd Value:

Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: YES

Remarks:

Joint:



Code: JAM

Description: Joint Angular Medium

Distance (ft): 6.9
Structural Grade: 3
O&M Grade: 0


Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

NO




Code: IWJ

Description: Infiltration Weeper Joint

Distance (ft): 22.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 4
Clock To: 5
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES

Remarks:



1/21/22

Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 22.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 4
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES

Remarks:

Code:

0.00 ft/min

85.48 ft

Description: Miscellaneous Water Level Sag

MWLS

Distance (ft): 85.5
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:


Value Percent: 15.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

......



Code: DAE

Description: **Deposits Attached Encrustation**

Distance (ft): 94.7 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 8 Clock To: 10

1st Value: 2nd Value:


5.000 Value Percent:

Continuous Index:

Within 8" of Joint:

YES

Remarks:



Code: DAE

Description: **Deposits Attached Encrustation**

Distance (ft): 98.6 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 2 5 Clock To: 1st Value:


2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: DAE


Description: Deposits Attached Encrustation

Distance (ft): 102.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S02
Within 8" of Joint: YES

Remarks:



Code: TF

Description: Tap Factory

Distance (ft): 123.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: ENCUSTATION COMING FROM THE TAP TO MAIN CONNECTION. ALSO H



Code: **TF**

Description: Tap Factory

Distance (ft): 141.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 1

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: ENCUSTATION COMING FROM THE TAP TO MAIN CONNECTION. ALSO H



1/21/22

Code: MWLS

Description: Miscellaneous Water Level Sag

Distance (ft): 159.6
Structural Grade: 2
O&M Grade: 0


Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S03
Within 8" of Joint: NO

Remarks:

159.62 ft



Code: MWLS

Description: Miscellaneous Water Level Sag


Distance (ft): 181.0
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F03
Within 8" of Joint: NO

Remarks:



Code: MWLS

Description: Miscellaneous Water Level Sag

Distance (ft): 186.3
Structural Grade: 4
O&M Grade: 0


Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 65.000
Continuous Index: S04
Within 8" of Joint: NO

Remarks:

itnin 8 O



Code: **JOM**

Description: Joint Offset Medium

Distance (ft): 189.8
Structural Grade: 3
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MCU

Description: Miscellaneous Camera Underwater

Distance (ft): 192.3
Structural Grade: 0
O&M Grade: 4


Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: S05
Within 8" of Joint: NO

Remarks:

n 8° of Joint:



Code: MCU

Description: **Miscellaneous Camera Underwater**


Distance (ft): 196.4 Structural Grade: 0 O&M Grade: 4

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

F05 Continuous Index: Within 8" of Joint: NO

Remarks:



Code: **MWLS**

Description: **Miscellaneous Water Level Sag**

Distance (ft): 197.6 Structural Grade: 4 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 65.000 Continuous Index: F04 Within 8" of Joint: NO

Remarks:



Code: **DSF**

Description: **Deposits Settled Fine**

Distance (ft): 200.2 Structural Grade: 0 2 O&M Grade: Clock Start/From: 5 Clock To: 7

1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: F01 Within 8" of Joint: YES

Remarks:



Code: DAE

Description: **Deposits Attached Encrustation**


5.000

Distance (ft): 200.2 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 7 5 Clock To: 1st Value:

2nd Value: Value Percent: Continuous Index:

F02 Within 8" of Joint: YES

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 201.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: **M-506-011**