Profile/Photo Observation Report



Date: 04/06/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 204.9 Owner: NA Pre Clean: No Pre-Cleaning P.O.#: Surveyor: Jen Costello PSR: P-506-012-011

Customer: Clean Date: 01/01/1900 Shape: C

Street: S COLORADO ST & W 7TH PL Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Yard Tape/Media #:

Purpose: Routine Assessment Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment: F_S_P_C pipe seperated, flow direction is marked wrong.

Location Details: Direction of Survey: **Downstream**

US MH: M-506-011 DS MH: M-506-012 Total Length Surveyed (ft): 7.8

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 2.00 2100 2.00 Structural Quick: Structural Rating: Structural Index: 2.00 2100 2.00 Overall Index: Overall Quick: Overall Rating:

P	osition	Code	Observation	Video (sec)	Grade
N(506-)011					
). ()	АМН	Manhole	10	NA
\()	MWL	Water Level	21	NA
7	.3	JOL	Joint Offset Large	47	S 2
7	.8	MSA	Abandoned Survey	59	NA
ш					
'					

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade: O&M Grade:	0
Clock Start/From: Clock To:	
1st Value: 2nd Value:	
Value Percent: Continuous Index:	
Within 8" of Joint: Remarks:	NO M-506-011

 AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 30.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

Code: JOL

Description: Joint Offset Large



Distance (ft): 7.3
Structural Grade: 2
O&M Grade: 0


Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 7.8
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO Remarks: jol