

Profile/Photo Observation Report						
Date: Pipe Length (ft) P.O.#: Customer:	04/07/2018 : 227.3	Weather: Owner: Surveyor: Clean Date:	NA Jen Coste 01/01/19	-	Coding: Pre Clean: PSR: Shape:	PACP 6.0 No Pre-Cleaning P-506-019-020 C
Street:	OFF S WISCONSIN ST	Г	Flow Contro	-	Not Controlled	
City:	Hobart, IN		Year Renev			
Location:	Yard		Tape/Media #:			
Purpose:	Purpose: Routine Assessment		Dia/Height:		10"	
Use:	Sanitary		Material:		VCP	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Details:			Direction o	f Survey:	Upstream	
US MH:	M-506-019	DS MH:	M-506-020		Total Length Surveyed (ft):	2.9
D&M Index:	0.00	O&M Quick:		0000	O&M Rating:	0.00
Structural Index:	0.00		uick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quicl	k:	0000	Overall Rating:	0.00





Code: Description:	AMH Manhole			
Distance (ft):	.0			
Structural Grade:	0			
O&M Grade:	0			
Clock Start/From:				
Clock To:				
1st Value:				
2nd Value:				
Value Percent:				
Continuous Index:				
Within 8" of Joint:	NO			
Remarks:	M-506-020			



Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 5.000 Continuous Index: Within 8" of Joint: NO Remarks:

Code:

Remarks:



Description:	Abandoned Survey
Distance (ft):	2.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO

MSA

not in pipe

Thursday, November 16, 2023