

# Profile/Photo Observation Report



|                   |                   |             |                     |            |                        |
|-------------------|-------------------|-------------|---------------------|------------|------------------------|
| Date:             | <b>03/28/2018</b> | Weather:    |                     | Coding:    | <b>PACP 6.0</b>        |
| Pipe Length (ft): | <b>218.0</b>      | Owner:      | <b>NA</b>           | Pre Clean: | <b>No Pre-Cleaning</b> |
| P.O.#:            |                   | Surveyor:   | <b>Selasie Honu</b> | PSR:       |                        |
| Customer:         |                   | Clean Date: | <b>01/01/1900</b>   | Shape:     | <b>C</b>               |

|                   |  |                             |                       |
|-------------------|--|-----------------------------|-----------------------|
| Street:           | <b>FOXCROFT STREET</b>                                 | Flow Control:               | <b>Not Controlled</b> |
| City:             | <b>Hobart, IN</b>                                      | Year Renewed:               |                       |
| Location:         | <b>Yard</b>  | Tape/Media #:               |                       |
| Purpose:          | <b>Routine Assessment</b>                              | Dia/Height:                 | <b>12"</b>            |
| Use:              | <b>Sanitary</b>  | Material:                   | <b>VCP</b>            |
| Drain Area:       | <b>NA</b>  | Lining:                     |                       |
| Category:         | <b>NA</b>  |                             |                       |
| Comment:          | <b>R_M at 8 ft nothing visible rocks in the tracks</b> |                             |                       |
| Location Details: |  | Direction of Survey:        | <b>Downstream</b>     |
| US MH:            | <b>M-507-011</b>                                       | DS MH:                      | <b>M-507-019A</b>     |
|                   |  | Total Length Surveyed (ft): | <b>9.4</b>            |

|                   |             |                   |             |                    |             |
|-------------------|-------------|-------------------|-------------|--------------------|-------------|
| O&M Index:        | <u>2.00</u> | O&M Quick:        | <u>2400</u> | O&M Rating:        | <u>8.00</u> |
| Structural Index: | <u>0.00</u> | Structural Quick: | <u>0000</u> | Structural Rating: | <u>0.00</u> |
| Overall Index:    | <u>2.00</u> | Overall Quick:    | <u>2400</u> | Overall Rating:    | <u>8.00</u> |

| Position         | Code | Observation                    | Video (sec) | Grade |
|------------------|------|--------------------------------|-------------|-------|
| <b>M-507-011</b> |      |                                |             |       |
| .0               | AMH  | Manhole                        | 10          | NA    |
| .0               | MWL  | Water Level                    | 21          | NA    |
| .0               | IS   | Infil Stain                    | 32          | NA    |
| 2.2              | DAE  | Deposits Attached Encrustation | 48          | M 2   |
| 4.6              | DSZ  | Deposits Settled Other         | 65          | M 2   |
| 9.4              | TFD  | Tap Factory Defective          | 86          | M 2   |
| 9.4              | DAE  | Deposits Attached Encrustation | 97          | M 2   |
| 9.4              | MSA  | Abandoned Survey               | 108         | NA    |

Camera Direction  
↓

**M-507-019A**



Code: **AMH**  
 Description: **Manhole**  
 Distance (ft): **.0**  
 Structural Grade: **0**  
 O&M Grade: **0**  
 Clock Start/From:  
 Clock To:  
 1st Value:  
 2nd Value:  
 Value Percent:  
 Continuous Index:  
 Within 8" of Joint: **NO**  
 Remarks: **M-507-011**

---

Code: **MWL**  
Description: **Water Level**



Distance (ft): **.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From:  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:

---

Code: **IS**  
Description: **Infil Stain**



Distance (ft): **.0**  
Structural Grade: **0**  
O&M Grade: **0**  
Clock Start/From: **8**  
Clock To: **12**  
1st Value:  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

Code: **DAE**  
Description: **Deposits Attached Encrustation**



Distance (ft): **2.2**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **8**  
Clock To: **4**  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks:

---

Code: **DSZ**  
Description: **Deposits Settled Other**



Distance (ft): **4.6**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **4**  
Clock To:  
1st Value:  
2nd Value:  
Value Percent: **10.000**  
Continuous Index:  
Within 8" of Joint: **YES**  
Remarks: **mixed material**

Code: **TFD**  
Description: **Tap Factory Defective**



Distance (ft): **9.4**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **3**  
Clock To:  
1st Value: **4.000**  
2nd Value:  
Value Percent:  
Continuous Index:  
Within 8" of Joint:  
Remarks: **DAE**

---

Code: **DAE**  
Description: **Deposits Attached Encrustation**



Distance (ft): **9.4**  
Structural Grade: **0**  
O&M Grade: **2**  
Clock Start/From: **3**  
Clock To: **4**  
1st Value:  
2nd Value:  
Value Percent: **5.000**  
Continuous Index:  
Within 8" of Joint: **NO**  
Remarks:

---



|                     |                         |
|---------------------|-------------------------|
| Code:               | <b>MSA</b>              |
| Description:        | <b>Abandoned Survey</b> |
| Distance (ft):      | <b>9.4</b>              |
| Structural Grade:   | <b>0</b>                |
| O&M Grade:          | <b>0</b>                |
| Clock Start/From:   |                         |
| Clock To:           |                         |
| 1st Value:          |                         |
| 2nd Value:          |                         |
| Value Percent:      |                         |
| Continuous Index:   |                         |
| Within 8" of Joint: | <b>NO</b>               |
| Remarks:            | <b>camera stopped</b>   |