

Profile/Ph	oto Observatio	n Report			RedZone
Date:	03/28/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft): 246.0	Owner:	NA	Pre Clean:	No Pre-Cleaning
P.O.#:		Surveyor:	Selasie Honu	PSR:	
Customer:		Clean Date:	01/01/1900	Shape:	c
Street:	FOXCROFT STREE	Т	Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Woods		Tape/Media #:		
Purpose:	Routine Assessme	ent	Dia/Height:	12"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:	F_S_R_M at 1 ft debris				
Location Detai	ls:		Direction of Surve	y: Upstream	
US MH:	M-507-019	DS MH:	M-507-019A	Total Length Surveyed (ft)	: 3.0
0&M Index:	3.00	O&M Quick:	3100	O&M Rating:	3.00
tructural Index:	2.00	Structural Qui	ck: 2100		2.00
Overall Index:	2.50	Overall Quick:	3121	Overall Rating:	5.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-507-019A




Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 5.000 Continuous Index: Within 8" of Joint: NO Remarks:



Code:	MWLS	
Description:	Water Level Sag	
	-	
Distance (ft):	.0	
Structural Grade:	2	
O&M Grade:	3	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:	10.000	
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:		



Code: Description: MSA Abandoned Survey

Distance (ft):	3.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	camera stopped