Profile/Photo Observation Report



Date: 10/09/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 239.0 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-507-012-011 Surveyor: Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: Colorado St. Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: **Downstream**

US MH: M-507-011 DS MH: M-507-012 Total Length Surveyed (ft): 3.3

1.50 2111 3.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 1.50 2111 3.00 Overall Index: Overall Quick: Overall Rating:

	Position	Code	Observation	Video (sec)	Grade
и (507- 0	11				
307		АМН	Manhole	10	NA
	0.	MWL	Water Level	21	NA
ш	\\\ <u>.</u> 0	DAE	Deposits Attached Encrustation	32	M 2
ш	\\.0	RFJ	Roots Fine Joint	44	M 1
ш	3.3	MSA	Abandoned Survey	61	NA

Code:

Description:



.0
0
0
NO
M-507-011

AMH

Manhole



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

Remarks:

5.000

Code: DAE

Description: **Deposits Attached Encrustation**



Distance (ft): .0 Structural Grade:

0 O&M Grade: 2 Clock Start/From: 9

Clock To: 3 1st Value:

2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): .0
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 9
Clock To: 3
1st Value:
2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: MSA

Description: Abandoned Survey

Distance (ft): 3.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: camera stopped