
Profile/Photo Observation Report						
Date:	10/08/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft)	: 208.6	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	Selasie Hon	u	PSR:	P-507-013-012
Customer:		Clean Date:	01/01/1900)	Shape:	с
Street:	CSOKASY LN		Flow Control:		Not Controlled	
City:	Hobart, IN		Year Renewe	d:		
Location:	Light Highway		Tape/Media	<i>‡</i> :		
Purpose:	Routine Assessment		Dia/Height:		12"	
Use:	Sanitary		Material:		VCP	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Detail	s:		Direction of S	urvey:	Upstream	
US MH:	M-507-012	DS MH:	M-507-013	Т	otal Length Surveyed (ft):	3.2
0&M Index:	0.00	O&M Quick:	(0000	O&M Rating:	0.00
tructural Index:	0.00	Structural Qu	uick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick	<: (0000	Overall Rating:	0.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-507-013



Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 5.000 Continuous Index: Within 8" of Joint: NO Remarks:

Code:	MSA
Description:	Abandoned Survey

Distance (ft):	3.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	camera stopped