## **Profile/Photo Observation Report**



Date: 03/27/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 325.0 Owner: NA Pre Clean: No Pre-Cleaning
P.O.#: Surveyor: Jen Costello PSR: P-507-023-013

Customer: Clean Date: 01/01/1900 Shape: C

Street: CSOKASY LN & S COLORADO ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment: F\_S\_P\_C at 3 ft debris. Flow direction wrong

Location Details: Direction of Survey: Upstream

US MH: M-507-013 DS MH: M-507-023 Total Length Surveyed (ft): 4.0

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Index: Overall Quick: Overall Rating:

|           | Position | Code | Observation      | Video (sec) | Grade |
|-----------|----------|------|------------------|-------------|-------|
| M(507-)02 | 23       |      |                  |             |       |
|           | .0       | AMH  | Manhole          | 11          | NA    |
| /         | 0.       | MWL  | Water Level      | 22          | NA    |
|           | 4.0      | MSA  | Abandoned Survey | 41          | NA    |
| M-507-01  | 13       |      |                  |             |       |

Code:



| Description:                                   | Manhole         |  |
|--|-----------------|--|
| Distance (ft): Structural Grade:               | .0<br>0         |  |
| O&M Grade:<br>Clock Start/From:                | 0               |  |
| Clock To:<br>1st Value:                        |                 |  |
| 2nd Value:<br>Value Percent:                   |                 |  |
| Continuous Index: Within 8" of Joint: Remarks: | NO<br>M-507-023 |  |
|  |                 |  |

**AMH** 



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

40.000

NO



Code: MSA

Description: **Abandoned Survey** 

Distance (ft): 4.0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks: debris under water

NO