

Profile/Ph	oto Observation	Report				RedZone
Date:	10/08/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft): 325.0	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	Selasie Honi	ı	PSR:	P-507-023-013
Customer:		Clean Date:	01/01/1900		Shape:	С
Street:	Csokasy Ln.		Flow Control:		Not Controlled	
City:	Hobart, IN		Year Renewed	l:		
Location:	Light Highway		Tape/Media #	:		
Purpose:	Routine Assessmen	t	Dia/Height:		12"	
Use:	Sanitary		Material:		VCP	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Detail	ls:		Direction of S	urvey:	Downstream	
US MH:	M-507-013	DS MH:	M-507-023	Tota	al Length Surveyed (ft):	5.1
0&M Index:	0.00	O&M Quick:	C	000	O&M Rating:	0.00
tructural Index:	0.00	Structural Qu	iick: 0	000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick		000	Overall Rating:	0.00





Code: Description:	AMH Manhole
Dictored (ft):	0
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-507-013



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	MSA
Description:	Abandoned Survey

Distance (ft):	5.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	camera stopped