Profile/Photo Observation Report

Location:



Date: 10/08/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 325.0 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-507-023-013 Surveyor: Selasie Honu

Customer: Clean Date: 01/01/1900 Shape:

Csokasy Ln. Flow Control: **Not Controlled** Street:

City: Hobart, IN Year Renewed:

Light Highway Purpose: **Routine Assessment** Dia/Height: 12" **VCP**

Use: Sanitary Material:

NA Lining: Drain Area: NA Category:

Comment: **Location Details:** Direction of Survey: Upstream

US MH: Total Length Surveyed (ft): M-507-013 DS MH: M-507-023 3.8

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

Tape/Media #:

Position	Code	Observation	Video (sec)	Grade
M(507-023				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
3.8	MSA	Abandoned Survey	40	NA
Camera Direction				

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-507-023

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:


Remarks:

5.000

NO

Code: MSA

Description: **Abandoned Survey**



Distance (ft): 3.8 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: camera stopped