Profile/Ph	oto Observatio	n Report			RedZone R 0 B 0 T I C S
Date:	04/05/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft)	: 229.3	Owner:	NA	Pre Clean:	No Pre-Cleaning
P.O.#:		Surveyor:	Jen Costello	PSR:	P-507-016-015
Customer:		Clean Date:	01/01/1900	Shape:	C
Street:	ALLEY BETWEEN	S DELAWARE ST &	<b>S</b> Flow Control:	Not Controll	ed
City:	Hobart, IN		Year Renewed:		
Location:	Yard		Tape/Media #:		
Purpose:	Routine Assessme	ent	Dia/Height:	10"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:	Flow direction is	wrong.			
Location Detail	s:		Direction of Sur	vey: Upstream	
US MH:	M-507-015	DS MH:	M-507-016	Total Length Surveyed (	(ft): <b>215.7</b>
0&M Index:	2.00	O&M Quick:	21	00 O&M Rating:	2.00
Structural Index:	0.00	Structural Qu	uick: 00	00 Structural Ratin	.g: <b>0.00</b>
Overall Index:	2.00	Overall Quicl	<: <b>21</b> 0	00 Overall Rating:	2.00

	Position	Code	Observation	Video (sec)	Grade
M(507-0	16				
	.0	AMH	Manhole	10	NA
	0.	MWL	Water Level	22	NA
_	39.7	TFA	Tap Factory Active	113	NA
	41.9	TFA	Tap Factory Active	130	NA
	117.8	TF	Tap Factory	294	NA
_	117.8	DAGS	Deposits Attached Grease	306	M 2
_	119.9	TFA	Tap Factory Active	323	NA
_	186.1	TFA	Tap Factory Active	468	NA
_	188.1	TF	Tap Factory	484	NA
5	215.7	AMH	Manhole	551	NA
Camera Direction	15				
M-507-0	15				




Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-507-016



Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 30.000 Continuous Index: Within 8" of Joint: NO Remarks:




Code: Description:	TFA Tap Factory Active
Distance (ft):	39.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	

Thursday, November 16, 2023



Code:	TFA
Description:	Tap Factory Active

Distance (ft):	41.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft): Structural Grade:	117.8 0
O&M Grade:	0
Clock Start/From: Clock To:	9
1st Value: 2nd Value:	4.000
Value Percent:	
Continuous Index: Within 8" of Joint:	
Remarks:	



Code:DAGSDescription:Deposits Attached Grease

Distance (ft):	117.8
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	9
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	




Code:	TFA
Description:	<b>Tap Factory Active</b>
D: 1 ((1)	440.0
Distance (ft):	119.9
Structural Grade:	0
O&M Grade:	0
	•

Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:TFADescription:Tap Factory Active

Distance (ft): 186.1 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 9 Clock To: 1st Value: 4.000 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:



Code: Description:	TF Tap Factory
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:	188.1 0 0 3 4.000
Continuous Index: Within 8" of Joint: Remarks:	



Code:	AMH
Description:	Manhole

Distance (ft):	215.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-507-015