

Profile/Ph	oto Observatio	n Report			RedZone
Date: Pipe Length (ft) P.O.#: Customer:	03/28/2018): 218.0	Weather: Owner: Surveyor: Clean Date:	NA Selasie Honu 01/01/1900	Coding: Pre Clean: PSR: Shape:	PACP 6.0 No Pre-Cleaning P-507-020-019 C
Street:	FOXCROFT STREE	т	Flow Control:	Not Controlle	d
City:	Hobart, IN		Year Renewed:		
Location:	Woods		Tape/Media #:		
Purpose:	Routine Assessme	ent	Dia/Height:	12"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:	P_C at 151 ft deb	ris . Flow directio	n wrong		
Location Detail	S:		Direction of Surv	vey: Upstream	
US MH:	M-507-019	DS MH:	M-507-020	Total Length Surveyed (f	t): 152.8
D&M Index:	0.00	O&M Quick:	000	00 O&M Rating:	0.00
Structural Index:	0.00	Structural Q	uick: 000	00 Structural Rating	.000
Overall Index:	0.00	Overall Quic	k: 000	00 Overall Rating:	0.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-507-020



Code: MWL Description: Water Level

.0
0
0
5.000
NO



Code: Description:	TB Tap Break-in
Distance (ft):	39.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	12
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	

Tuesday, December 8, 2020



Code:	TF
Description:	Tap Factory

Distance (ft):	100.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	MSA
Description:	Abandoned Survey

Distance (ft):	152.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	CAMERA STOPPED