## **Profile/Photo Observation Report**



Date: 03/28/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 299.6 Owner: NA Pre Clean: No Pre-Cleaning
P.O.#: Surveyor: Selasie Honu PSR: P-507-029-020

Customer: Clean Date: 01/01/1900 Shape: C

Street: OFF S DEKALB ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Woods Tape/Media #:

Purpose: Routine Assessment Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment: R\_M at 157 ft debris . Flow direction wrong

Location Details: Direction of Survey: **Upstream** 

US MH: M-507-020 DS MH: M-507-029 Total Length Surveyed (ft): 158.2

2.00 2400 8.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2400 8.00 Overall Index: Overall Quick: Overall Rating:

	Position	Code	Observation	Video (sec)	Grade
507-0	029				
	0. //	AMH	Manhole	10	NA
	0.	MWL	Water Level	21	NA
	21.2	IW	Infil Weeper	75	M 2
	63.6	ТВ	Tap Break-in	172	NA
	71.2	TFC	Tap Factory Capped	199	NA
	113.5	DAE(S01)	Deposits Attached Encrustation	296	M 2
	121.7	TF	Tap Factory	325	NA
	122.4	DAE(F01)	Deposits Attached Encrustation	340	M 2
ш.	122.5	IW	Infil Weeper	351	M 2
	158.2	MSA	Abandoned Survey	434	NA
	130.2		Abundoned Survey	434	IVA
	150.2	WIST.	Abundoned Survey	757	IVA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-507-029

AMH



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO





Distance (ft): 21.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 3
Clock To:

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: TB

Description: Tap Break-in

Distance (ft): 63.6 Structural Grade: 0 0 O&M Grade: Clock Start/From: 10

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



TFC Code:

Description: **Tap Factory Capped** 

Distance (ft): 71.2 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 10

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 113.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:


1st Value: 2nd Value:

Value Percent: 10.000
Continuous Index: S01
Within 8" of Joint: YES

Remarks:

Code: **TF** 

Description: Tap Factory



Distance (ft): 121.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Code: DAE

Description: Deposits Attached Encrustation



2nd Value:

Value Percent: 10.000
Continuous Index: F01
Within 8" of Joint: YES

Remarks:

Code: IW

Description: Infil Weeper



Distance (ft): 122.5
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Remarks:

Within 8" of Joint:



Code: MSA

Description: Abandoned Survey

Distance (ft): 158.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: camera stopped