Profile/Photo Observation Report



Date: 10/10/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 210.4 Owner: NA Pre Clean: **Not Known** P.O.#: PSR: P-507-026-025 Surveyor: Selasie Honu

Customer: Clean Date: 01/01/1900 Shape: C

Street: ALLEY BETWEEN S DEKALB ST & S C Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Routine Assessment Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: **NA** Lining:

Category: NA
Comment: NULL - DC @ MH-M-507-059

Location Details: Direction of Survey: **Downstream**

US MH: M-507-025 DS MH: M-507-026 Total Length Surveyed (ft): 70.2

0000 0.00 0.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 0.00 0000 0.00 Overall Rating: Overall Index: Overall Quick:

	Code	Observation	Video (sec)	Grade
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
13.0	TF	Tap Factory	58	NA
14.8	TF	Tap Factory	73	NA
70.2	MSA	Abandoned Survey	195	NA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-507-025

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO



Code: **TF**

Description: Tap Factory

Distance (ft): 13.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To: 1st Value:

1st Value: 4.000 2nd Value:

Value Percent:
Continuous Index:
Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 14.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value:

4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 70.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: camera underwater