


Profile/Photo Observation Report




Date:	12/11/2024	Weather:		Coding:	PACP 7.0
Pipe Length (ft):	235.0	Owner:	City of Hobart	Pre Clean:	Heavy Cleaning
P.O.#:	YES502259	Surveyor:	S. Bucklin	PSR:	P-507-035-028
Customer:	City of Hobart	Clean Date:	09/27/2024	Shape:	C

Street:	South Dekalb Street	Flow Control:	Not Controlled
City:	Hobart, IN	Year Renewed:	
Location:	Yard	Tape/Media #:	
Purpose:	Sewer System Evaluation Survey (SS	Dia/Height:	10"
Use:	Sanitary Sewage Pipe	Material:	VCP
Drain Area:		Lining:	None
Category:	NA		
Comment:			
Location Details:		Direction of Survey:	Downstream
US MH:	M-507-035	DS MH:	M-507-028
		Total Length Surveyed (ft):	116.8

O&M Index:	2.00	O&M Quick:	3123	O&M Rating:	10.00
Structural Index:	3.17	Structural Quick:	5341	Structural Rating:	73.00
Overall Index:	2.96	Overall Quick:	5341	Overall Rating:	83.00

	Position	Code	Observation	Video (sec)	Grade
	.0	AMH	Manhole	0	NA
	.0	MWL	Miscellaneous Water Level	77	NA
	2.6	SSS	Surface Damage Surface Spalling	133	S 2
	2.7	TBD	Tap Break-in/Hammer Defective	150	M 3
	12.2	MWLS(S01)	Miscellaneous Water Level Sag	207	S 3
	29.0	LL	Line Left	287	M 1
	32.4	SSS	Surface Damage Surface Spalling	313	S 2
	54.2	HVV	Hole Void Visible	459	S 5
	54.6	TBI	Tap Break-in Intruding	478	M 2
	70.8	SSS	Surface Damage Surface Spalling	681	S 2
	86.8	RPPD	Point Repair Patch Patch Defective	958	S 4
	87.4	TBI	Tap Break-in Intruding	1008	M 2
	87.4	BSV	Broken Soil Visible	1021	S 5
	90.8	MWLS(F01)	Miscellaneous Water Level Sag	1068	S 3
	116.4	HSV	Hole Soil Visible	1237	S 5
	116.6	TBI	Tap Break-in Intruding	1269	M 2
	116.8	MSA	Miscellaneous Survey Abandoned	1303	NA




Code: **AMH**
 Description: **Manhole**

 Distance (ft): **.0**
 Structural Grade: **0**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks: **M-507-035**



Code: **MWL**
Description: **Miscellaneous Water Level**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **5.000**
Continuous Index:
Within 8" of Joint: **NO**
Remarks:



Code: **SSS**
Description: **Surface Damage Surface Spalling**

Distance (ft): **2.6**
Structural Grade: **2**
O&M Grade: **0**
Clock Start/From: **9**
Clock To: **12**
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks:



Code: **TBD**
Description: **Tap Break-in/Hammer Defective**

Distance (ft): **2.7**
Structural Grade: **0**
O&M Grade: **3**
Clock Start/From: **10**
Clock To:
1st Value: **6.000**
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks: **Defective**




Code: **MWLS**
Description: **Miscellaneous Water Level Sag**

Distance (ft): **12.2**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **35.000**
Continuous Index: **S01**
Within 8" of Joint: **NO**
Remarks:




Code: **LL**
Description: **Line Left**

Distance (ft): **29.0**
Structural Grade: **0**
O&M Grade: **1**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **5.000**
Continuous Index:
Within 8" of Joint: **NO**
Remarks:




Code: **SSS**
Description: **Surface Damage Surface Spalling**

Distance (ft): **32.4**
Structural Grade: **2**
O&M Grade: **0**
Clock Start/From: **2**
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks:




Code: **HVV**
 Description: **Hole Void Visible**

Distance (ft): **54.2**
 Structural Grade: **5**
 O&M Grade: **0**
 Clock Start/From: **9**
 Clock To: **12**
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks:




Code: **TBI**
 Description: **Tap Break-in Intruding**

Distance (ft): **54.6**
 Structural Grade: **0**
 O&M Grade: **2**
 Clock Start/From: **10**
 Clock To:
 1st Value: **6.000**
 2nd Value: **2.000**
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:




Code: **SSS**
 Description: **Surface Damage Surface Spalling**

Distance (ft): **70.8**
 Structural Grade: **2**
 O&M Grade: **0**
 Clock Start/From: **12**
 Clock To: **1**
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks:




Code: **RPPD**
 Description: **Point Repair Patch Patch Defective**

Distance (ft): **86.8**
 Structural Grade: **4**
 O&M Grade: **0**
 Clock Start/From: **9**
 Clock To: **1**
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks: **Soil visible**



Code: **TBI**
 Description: **Tap Break-in Intruding**

Distance (ft): **87.4**
 Structural Grade: **0**
 O&M Grade: **2**
 Clock Start/From: **11**
 Clock To:
 1st Value: **6.000**
 2nd Value: **2.000**
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks: **CONSTANTLY DRIPPING WATER. VOID UNDER THE SERVICE.**




Code: **BSV**
 Description: **Broken Soil Visible**

Distance (ft): **87.4**
 Structural Grade: **5**
 O&M Grade: **0**
 Clock Start/From: **9**
 Clock To: **12**
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks:




Code: **MWLS**
Description: **Miscellaneous Water Level Sag**

Distance (ft): **90.8**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **35.000**
Continuous Index: **F01**
Within 8" of Joint: **NO**
Remarks:



Code: **HSV**
Description: **Hole Soil Visible**

Distance (ft): **116.4**
Structural Grade: **5**
O&M Grade: **0**
Clock Start/From: **12**
Clock To: **3**
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks:



Code: **TBI**
 Description: **Tap Break-in Intruding**

Distance (ft): **116.6**
 Structural Grade: **0**
 O&M Grade: **2**
 Clock Start/From: **2**
 Clock To:
 1st Value: **6.000**
 2nd Value: **5.000**
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks: **Active**



Code: **MSA**
 Description: **Miscellaneous Survey Abandoned**

Distance (ft): **116.8**
 Structural Grade: **0**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks: **CAMERA CANT MAKE IT PAST PROTRUDING TAP. MADE IT TO THE**