Profile/Photo Observation Report



Date: 03/29/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 179.3 Owner: NA Pre Clean: No Pre-Cleaning P.O.#: Surveyor: Jen Costello PSR: P-507-032-031

Customer: Clean Date: 01/01/1900 Shape: C

Street: CSOKASY LN Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Yard Tape/Media #:

Purpose: Routine Assessment Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: **NA** Lining:

Category: NA
Comment: Flow direction wrong

Location Details: Direction of Survey: **Downstream**

US MH: M-507-031 DS MH: M-507-032 Total Length Surveyed (ft): 150.0

1.75 2311 7.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 1.75 2311 7.00 Overall Rating: Overall Index: Overall Quick:


	Position	Code	Observation	Video (sec)	Grade
507-0	031				
\checkmark	0. //	AMH	Manhole	10	NA
	0.	MWL	Water Level	21	NA
	43.2	TBI	Tap Break-in Intruding	119	M 2
	43.2	RFC	Roots Fine Connection	130	M 1
	45.7	TFA	Tap Factory Active	147	NA
	88.1	TFA	Tap Factory Active	244	NA
	140.5	TF	Tap Factory	361	NA
	142.6	TFA	Tap Factory Active	377	NA
	143.0	DAE	Deposits Attached Encrustation	390	M 2
	143.0	IW	Infil Weeper	401	M 2
	150.0	AMH	Manhole	426	NA

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-507-031		

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

Code: TBI

Description: Tap Break-in Intruding



Distance (ft): 43.2
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2

Clock To:

 1st Value:
 4.000

 2nd Value:
 3.000

Value Percent: Continuous Index: Within 8" of Joint:

Remarks: ROOTS



Code: RFC

Description: Roots Fine Connection

Distance (ft): 43.2
Structural Grade: 0

O&M Grade: 1

Clock Start/From: 1

Clock To: 2


1st Value:

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: TFA

Description: Tap Factory Active

Distance (ft): 45.7
Structural Grade: 0

O&M Grade: 0


Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: TFA

Description: Tap Factory Active


Distance (ft): 88.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 140.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 9

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: TFA

Description: Tap Factory Active

Distance (ft): 142.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 143.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 9
Clock To: 10


1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: IW

Description: Infil Weeper

Distance (ft): 143.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 9
Clock To: 10

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: AMH
Description: Manhole

Distance (ft): 150.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: M-507-032