Profile/Ph	noto Observation	Report			RedZor
Date:	04/13/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft	t): <b>134.5</b>	Owner:	NA	Pre Clean:	No Pre-Cleaning
P.O.#:		Surveyor:	Jen Costello	PSR:	P-507-039.3-039.2
Customer:		Clean Date:	01/01/1900	Shape:	с
Street:	W 10TH ST		Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Yard		Tape/Media #:		
Purpose:	Routine Assessment	t	Dia/Height:	10"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Detai	ils:		Direction of Surve	y: Downstream	
US MH:	M-507-039.2	DS MH:	M-507-039.3	Total Length Surveyed (ft):	112.7
D&M Index:	1.08	O&M Quick:	221C	O&M Rating:	26.00
Structural Index	4.50	Structural Qu	uick: 5141	Structural Rating:	9.00
Overall Index:	1.35	Overall Quic		Overall Rating:	35.00

	Position	Code	Observation	Video (sec)	Grade
M-507	7-039.2				
	.0	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
	1.4	В	Broken	36	S 5
	1.4	RFJ	Roots Fine Joint	47	M 1
	4.4	RFJ(SO1)	Roots Fine Joint	64	M 1
	22.4	FM	Fracture Multiple	112	S 4
	34.3	TBI	Tap Break-in Intruding	149	M 2
- 1	40.4	TFC	Tap Factory Capped	176	NA
- H	73.9	TBI	Tap Break-in Intruding	256	M 2
5	110.7	RFJ(F01)	Roots Fine Joint	341	M 1
ecti	112.7	AMH	Manhole	357	NA
Camera Direction					
м-\$07	7-039.3				



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-507-039.2

\_




Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	




Code: Description:	B Broken
Distance (ft):	1.4
Structural Grade:	5
O&M Grade:	0
Clock Start/From:	1
Clock To:	3
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:**RFJ**Description:**Roots Fine Joint** 

Distance (ft):	1.4
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	1
Clock To:	3
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	RFJ
Description:	<b>Roots Fine Joint</b>
Distance (ft):	4.4
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	S01

YES

Within 8" of Joint:

Remarks:




Code:FMDescription:Fracture Multiple

Distance (ft):	22.4
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	8
Clock To:	10
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	

2nd Value:

Remarks:

Value Percent: Continuous Index: Within 8" of Joint:




Code:	ТВІ
Description:	Tap Break-in Intruding
Distance (ft):	34.3
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	9
Clock To:	
1st Value:	4.000

1.000



Code:TFCDescription:Tap Factory Capped

Distance (ft):	40.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	TBI
Description:	Tap Break-in Intruding
Distance (ft):	73.9
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	9
Clock To: 1st Value: 2nd Value:	4.000 1.000
Value Percent: Continuous Index: Within 8" of Joint: Remarks:	



Code:RFJDescription:Roots Fine Joint

Distance (ft):	110.7
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	F01
Within 8" of Joint:	YES
Remarks:	

Code:



Description:	Manhole
Distance (ft):	112.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	

AMH

Continuous Index: Within 8" of Joint: NO Remarks: M-507-039.3