Profile/Photo Observation Report



Date: 03/26/2018 Weather: **PACP 6.0** Coding:

Pipe Length (ft): 317.3 Owner: NA Pre Clean: No Pre-Cleaning P.O.#: **Justin Gonzales** PSR: P-507-049-050 Surveyor:

Customer: 01/01/1900 Clean Date: Shape:

Flow Control: **Not Controlled** Street: **FOXCROFT STREET**

City: Hobart, IN Year Renewed: Tape/Media #: Location: **Light Highway**

Purpose: **Routine Assessment** Dia/Height: 8" **PVC** Use: Sanitary Material:

NΑ Drain Area: Lining:

Category: NA P_C at 283 ft debris

Comment:


Location Details: Direction of Survey: **Downstream**

US MH: Total Length Surveyed (ft): M-507-049 DS MH: M-507-050 284.3

2.00 **2J00** 116.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 **2J00** 116.00 Overall Index: Overall Quick: Overall Rating:


	Position	Code	Observation	Video (sec)	Grade
507-	049				
	0.	AMH	Manhole	10	NA
ш	0.	MWL	Water Level	21	NA
ш	0.	DAZ(S01)	Deposits Attached Other	32	M 2
п	35.8	TF	Tap Factory	116	NA
н	105.6	TF	Tap Factory	267	NA
н	189.9	DAGS	Deposits Attached Grease	447	M 2
ш	190.7	TF	Tap Factory	461	NA
ш	274.4	TF	Tap Factory	640	NA
Ш	284.3	MSA	Abandoned Survey	672	NA
ш	284.3	DAZ(F01)	Deposits Attached Other	683	M 2
	11				

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-507-049		

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:


Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO




Code: DAZ

Description: **Deposits Attached Other**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 7 Clock To: 5 1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: **S01** Within 8" of Joint: YES Remarks: WANDER



Code: **TF**

Description: Tap Factory


Distance (ft): 35.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 105.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: DAGS

Description: Deposits Attached Grease

Distance (ft): 189.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 3
Clock To: 4
1st Value:

2nd Value:


Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF**

Description: Tap Factory


Distance (ft): 190.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 274.4
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:

Code: MSA

Description: Abandoned Survey



Distance (ft): 284.3 Structural Grade: 0


O&M Grade: **0**

Clock Start/From: Clock To:

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: ROBOT HAS STOPPED



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 284.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: YES

Remarks: WANDER