
Profile/Ph	oto Observatior	n Report				RedZon
Date:	03/26/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft	:): 274.5	Owner:	NA		Pre Clean:	No Pre-Cleaning
P.O.#:		Surveyor:	Justin Go	nzales	PSR:	P-507-062-063
Customer:		Clean Date	e: 01/01/19	00	Shape:	C
Street:	FOXCROFT STREET	Г	Flow Contr	ol:	Not Controlled	
City:	Hobart, IN		Year Renev	wed:		
Location:	Light Highway		Tape/Med	ia #:		
Purpose:	Routine Assessme	ent	Dia/Height	:	8"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:	Flow direction wro	ong				
Location Detai	ls:		Direction o	of Survey:	Upstream	
US MH:	M-507-063	DS MH:	M-507-062	Т	otal Length Surveyed (ft)	: 287.6
0&M Index:	0.00	O&M Quick		0000	O&M Rating:	0.00
Structural Index	2.00	Structural C	Quick:	2100	Structural Rating:	2.00
Overall Index:	2.00	Overall Qui	ck:	2100	Overall Rating:	2.00

	Position	Code	Observation	Video (sec)	Grade
M(507-	062				
\square	0.	AMH	Manhole	10	NA
- 11	.0	MWL	Water Level	21	NA
- 11	41.8	TF	Tap Factory	116	NA
-	44.3	TF	Tap Factory	132	NA
- 11	100.0	TF	Tap Factory	256	NA
	162.3	TF	Tap Factory	393	NA
- 11	/ 172.4	TF	Tap Factory	425	NA
	172.4	IS	Infil Stain	436	NA
- 11	174.6	JSL	Joint Separated Large	452	S 2
5	176.1	IS	Infil Stain	466	NA
e Cti	191.3	MGO	General Observation	508	NA
ä	287.6	AMH	Manhole	712	NA
Camera Direction					
M(507)	063				




AMH Manhole
.0
0
0
NO
M-507-062

_




Code: MWL Description: Water Level


Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	41.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	TF
Description:	Tap Factory
Distance (ft):	44.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Distance (ft):100.0Structural Grade:0O&M Grade:0Clock Start/From:10Clock To:4.0002nd Value:4.000Value Percent:5.000Continuous Index:5.000Within 8" of Joint:5.000	Code: Description:	TF Tap Factory
Remarks:	Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:	0 0 10



Code:	TF
Description:	Tap Factory

Distance (ft):	162.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	2
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:	172.4 0 0 10 4.000



Code:	IS
Description:	Infil Stain
Distance (ft):	172.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	7
Clock To:	11
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES



Code:	JSL
Description:	Joint Separated Large


Remarks:

Distance (ft):	174.6
Structural Grade:	2
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	IS
Description:	Infil Stain

Distance (ft):	176.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	7
Clock To:	9
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	MGO
Description:	General Observation

Distance (ft):	191.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	LARVAE ON LENS

TAN.	
	No.

Code:	AMH
Description:	Manhole

Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent:	287.6 0 0
Continuous Index: Within 8" of Joint: Remarks:	NO M-507-063