
Profile/Photo Observation Report RedZone						
Date: Pipe Length (ft) P.O.#: Customer:	04/12/2018): 173.3	Weather: Owner: Surveyor: Clean Date:	NA Jen Costell 01/01/190		Coding: Pre Clean: PSR: Shape:	PACP 6.0 No Pre-Cleaning P-507-085-084 C
Street:	FOXCROFT STREET		Flow Contro	l:	Not Controlled	
City:	Hobart, IN	Year Rene		ed:		
Location:	Yard		Tape/Media	#:		
Purpose:	Routine Assessmen	t	Dia/Height:		10"	
Use:	Sanitary		Material:		PVC	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Detail	s:		Direction of	Survey:	Downstream	
US MH:	M-507-084	DS MH:	M-507-085	-	Total Length Surveyed (ft):	6.6
O&M Index:	0.00	O&M Quick:		0000	O&M Rating:	0.00
Structural Index:	0.00	Structural Qu	uick:	0000	Structural Rating:	0.00
Overall Index:	0.00	Overall Quick	<:	0000	Overall Rating:	0.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-507-084



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	

Code:



Description:	Abandoned Survey	
Distance (ft):	6.6	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	debris under water	

MSA