Profile/Photo Observation Report



Date: 04/11/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 234.1 Owner: NA Pre Clean: **Not Known** P.O.#: Surveyor: Jen Costello PSR: P-603-002-001

Customer: Clean Date: 01/01/1900 Shape: C

Street: W 39TH PL Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: **Downstream**

US MH: M-603-002 DS MH: M-603-001 Total Length Surveyed (ft): 5.5

4.00 4.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 4.00 4.00 Overall Index: Overall Quick: Overall Rating:

Position	Code	Observation	Video (sec)	Grade
603-002				
.0	АМН	Manhole	10	NA
.0	MWL	Water Level	21	NA
\\0	MCU(S01)	Camera Underwater	32	M 4
5.5	MSA	Abandoned Survey	55	NA
5.5	MCU(F01)	Camera Underwater	66	M 4

Code:



Manhole	
.0	
0	
0	
NO	
M-603-002	

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 100.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

Code:

100.000



MCU

Description: Camera Underwater

Distance (ft): .0
Structural Grade: 0
O&M Grade: 4
Clock Start/From:
Clock To:
1st Value:

2nd Value: Value Percent: Continuous Index:

Continuous Index: **S01**Within 8" of Joint: **NO**

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 5.5
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: MCU

Code: MCU

Description: Camera Underwater



Distance (ft): 5.5
Structural Grade: 0
O&M Grade: 4

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: F01
Within 8" of Joint: NO

Remarks: