
| Date: | 04/11/2018 | Weather: | | Coding: | PACP 6.0 |
|-------------------|------------|---------------|---------------------|-----------------------------|---------------|
| Pipe Length (ft): | 234.1 | Owner: | NA | Pre Clean: | Not Known |
| P.O.#: | | Surveyor: | Jen Costello | PSR: | P-603-002-001 |
| Customer: | | Clean Date: | 01/01/1900 | Shape: | c |
| Street: | W 40th ave | | Flow Control: | Not Controlled | |
| City: | Hobart, IN | | Year Renewed: | | |
| Location: | Other | | Tape/Media #: | | |
| Purpose: | Not Known | | Dia/Height: | 10" | |
| Use: | Sanitary | | Material: | VCP | |
| Drain Area: | NA | | Lining: | | |
| Category: | NA | | | | |
| Comment: | | | | | |
| Location Details | 1 | | Direction of Survey | Downstream | |
| US MH: | M-603-002 | DS MH: | M-603-001 | Total Length Surveyed (ft): | 5.5 |
| D&M Index: | 4.00 | O&M Quick: | 4100 | O&M Rating: | 4.00 |
| Structural Index: | 0.00 | Structural Qu | uick: 0000 | Structural Rating: | 0.00 |
| Overall Index: | 4.00 | Overall Quick | 44.00 | Overall Rating: | 4.00 |





| Code: Description: | AMH Manhole |
|-----------------------|----------------|
| | |
| Distance (ft): | .0 |
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | |
| Clock To: | |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Continuous Index: | |
| Within 8" of Joint: | NO |
| Remarks: | M-603-002 |



Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 100.000 Continuous Index: Within 8" of Joint: NO Remarks:



| Code: | MCU | |
|--------------|-------------------|--|
| Description: | Camera Underwater | |
| | | |
| | | |

| Distance (ft): | .0 |
|---------------------|-----|
| Structural Grade: | 0 |
| O&M Grade: | 4 |
| Clock Start/From: | |
| Clock To: | |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Continuous Index: | S01 |
| Within 8" of Joint: | NO |
| Remarks: | |



Code: MSA Description: Abandoned Survey

MCU

Camera Underwater

| Distance (ft): | 5.5 |
|---------------------|-----|
| Structural Grade: | 0 |
| O&M Grade: | 0 |
| Clock Start/From: | |
| Clock To: | |
| 1st Value: | |
| 2nd Value: | |
| Value Percent: | |
| Continuous Index: | |
| Within 8" of Joint: | NO |
| Remarks: | MCU |

| Code: |
|--------------|
| Description: |
| |

| Distance (ft): | 5.5 | |
|---------------------|-----|--|
| Structural Grade: | 0 | |
| O&M Grade: | 4 | |
| Clock Start/From: | | |
| Clock To: | | |
| 1st Value: | | |
| 2nd Value: | | |
| Value Percent: | | |
| Continuous Index: | F01 | |
| Within 8" of Joint: | NO | |
| Remarks: | | |