Profile/Photo Observation Report



Date: 08/05/2023 Weather: **PACP 7.0** Coding: Pipe Length (ft): 158.0 Owner: **City of Hobart** Pre Clean: **Heavy Cleaning** P.O.#: S. Bucklin PSR: P-603-010-009 YES502259 Surveyor: Customer: **City of Hobart** Clean Date: 03/25/2023 Shape:

Street: West 39th Place Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Easement/Right of Way Tape/Media #:

Purpose:Routine AssessmentDia/Height:10"Use:Sanitary Sewage PipeMaterial:VCPDrain Area:Lining:None

Category: NA

Comment:

Location Details: Direction of Survey: **Downstream**

US MH: M-603-009 DS MH: M-603-010 Total Length Surveyed (ft): 158.0

 O&M Index:
 1.64
 O&M Quick:
 4133
 O&M Rating:
 113.00

 Structural Index:
 2.79
 Structural Quick:
 4B32
 Structural Rating:
 134.00


 Overall Index:
 2.11
 Overall Quick:
 4B35
 Overall Rating:
 247.00

	Position	Code	Observation	Video (sec)	Grade
VI(603-)	009				
	0.	AMH	Manhole	0	NA
-11	0.	MWL	Miscellaneous Water Level	83	NA
-	√ 2.1	В	Broken	141	S 4
ш	1\\2.2	RFJ	Roots Fine Joint	189	M 1
	1 8.3	FM(S01)	Fracture Multiple	287	S 4
ш	10.5	MWLS(S02)	Miscellaneous Water Level Sag	310	S 2
	15.2	JOMD	Joint Offset Medium Defective	379	S 3
	15.2	RFJ	Roots Fine Joint	393	M 1
ш	16.9	MWLS(F02)	Miscellaneous Water Level Sag	418	S 2
	1 19.0	MWLS(S03)	Miscellaneous Water Level Sag	437	S 2
	21.6	TFD	Tap Factory Defective	501	M 3
	22.4	DSF(S04)	Deposits Settled Fine	521	M 2
	23.9	ISB	Infiltration Stain Barrel	542	M 1
	24.6	TFA	Tap Factory Activity	593	NA
ш	27.1	RFJ(S05)	Roots Fine Joint	663	M 1
	27.1	FM(F01)	Fracture Multiple	680	S 4
	33.2	CS	Crack Spiral	726	S 2
	39.0	LL	Line Left	785	M 1
	42.5	FH4(S06)	Fracture Longitudinal Hinge, 4	862	S 4

	44.4	MWLS(F03)	Miscellaneous Water Level Sag	888	S 2		
	46.8	MWLS(S07)	Miscellaneous Water Level Sag	910	S 2		
Ш	54.5	FH4(F06)	Fracture Longitudinal Hinge, 4	948	S 4		
- 11	61.0	FM(S08)	Fracture Multiple	995	S 4		
- 11	66.1	DR(S09)	Deformed Rigid	1038	S 4		
- 11	67.0	RFB(S10)	Roots Fine Barrel	1053	M 2		
- 11	68.3	TBI	Tap Break-in Intruding	1100	M 2		
- 11	73.7	TFD	Tap Factory Defective	1160	M 3		
- 11	75.7	DR(F09)	Deformed Rigid	1187	S 4		
- 11	76.0	RMB	Roots Medium Barrel	1215	M 4		
- 11	76.0	RFL	Roots Fine Lateral	1219	M 1		
- 11	76.9	TFD	Tap Factory Defective	1231	M 3		
н	97.7	RFB(F10)	Roots Fine Barrel	1333	M 2		
- 11	97.7	FM(F08)	Fracture Multiple	1342	S 4		
- 11	108.7	JOMD	Joint Offset Medium Defective	1396	S 3		
- #4	118.8	MWLS(F07)	Miscellaneous Water Level Sag	1456	S 2		
- 11	119.4	FM(S11)	Fracture Multiple	1496	S 4		
- 11	122.6	FM(F11)	Fracture Multiple	1546	S 4		
- 11	122.6	MWLS(S12)	Miscellaneous Water Level Sag	1554	S 2		
- 11	131.7	FH3	Fracture Longitudinal Hinge, 3	1620	S 4		
- 11	138.9	TFC	Tap Factory Capped	1775	NA		
- 11	141.9	TF	Tap Factory	1810	NA		
- 11	144.4	DAE	Deposits Attached Encrustation	1859	M 2		
	153.9	RFJ(F05)	Roots Fine Joint	1949	M 1		
	156.4	MWLS(F12)	Miscellaneous Water Level Sag	1973	S 2		
Ш	156.4	DSF(F04)	Deposits Settled Fine	1983	M 2		
	158.0	AMH	Manhole	2077	NA		
M-603	010 010						



Code:	AMH Manhole
Description:	iviannoie
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-603-009



Description: Miscellaneous Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: B

Description: Broken

Distance (ft): 2.1
Structural Grade: 4

O&M Grade: 0

Clock Start/From: 4

Clock To: 7

1st Value:

2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: RFJ

Description: **Roots Fine Joint**

Distance (ft): 2.2 Structural Grade: 0 1 O&M Grade: Clock Start/From: 8 Clock To: 4

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: FΜ

Description: **Fracture Multiple**

Distance (ft): 8.3 Structural Grade: 4 O&M Grade: 0 Clock Start/From: 12 12 Clock To:

1st Value: 2nd Value: Value Percent: Continuous Index:

S01 Within 8" of Joint: YES



Description: Miscellaneous Water Level Sag


Distance (ft): 10.5
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000
Continuous Index: S02
Within 8" of Joint: NO

Remarks:



Code: **JOMD**

Description: Joint Offset Medium Defective

Distance (ft): 15.2
Structural Grade: 3
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 15.2
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 9
Clock To: 11

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: MWLS

Description: Miscellaneous Water Level Sag

Distance (ft): 16.9
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 15.000
Continuous Index: F02
Within 8" of Joint: NO



Description: Miscellaneous Water Level Sag

Distance (ft): 19.0 Structural Grade: 2

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000
Continuous Index: S03
Within 8" of Joint: NO

Remarks:



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 21.6
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 11

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: CAPPED. TAP BROKEN.



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 22.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 5
Clock To: 7

1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S04
Within 8" of Joint: YES

Remarks:



Code: ISB

Description: Infiltration Stain Barrel

Distance (ft): 23.9
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 3
Clock To:
1st Value:
2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: TFA

Description: Tap Factory Activity

Distance (ft): 24.6
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES

YES



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 27.1
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:
Value Percent:
Continuous Index: \$05

Within 8" of Joint:



Code: FM
Description: Fracture Multiple

Distance (ft): 27.1
Structural Grade: 4

O&M Grade: 0

Clock Start/From: 12

Clock To: 12

1st Value: 2nd Value: Value Percent:

Continuous Index: F01
Within 8" of Joint: YES

Remarks:



Code: CS

Description: Crack Spiral

Distance (ft): 33.2
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 1
Clock To: 2
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: YES



Code: LL

Description: Line Left

Distance (ft): 39.0 Structural Grade: 0

O&M Grade: 1

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: FH4

Description: Fracture Longitudinal Hinge, 4

Distance (ft): 42.5
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 12
Clock To: 12
1st Value:
2nd Value:

Value Percent: Continuous Index:

Continuous Index: S06
Within 8" of Joint: YES



Description: Miscellaneous Water Level Sag

Distance (ft): 44.4
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000
Continuous Index: F03
Within 8" of Joint: NO

Remarks:



Code: MWLS

Description: Miscellaneous Water Level Sag

Distance (ft): 46.8
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000
Continuous Index: S07
Within 8" of Joint: NO



Code: FH4

Description: Fracture Longitudinal Hinge, 4

Distance (ft): 54.5
Structural Grade: 4

O&M Grade: 0


Clock Start/From: 12

Clock To: 12

1st Value: 2nd Value: Value Percent:

Continuous Index: F06
Within 8" of Joint: YES

Remarks:



Code: FM

Description: Fracture Multiple

Distance (ft): 61.0
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:

Continuous Index: \$08
Within 8" of Joint: YES

Remarks:

Value Percent:



Code: DR

Description: Deformed Rigid

Distance (ft): 66.1
Structural Grade: 4

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: S09
Within 8" of Joint: NO

Remarks:




Code: RFB

Description: Roots Fine Barrel

Distance (ft): 67.0
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:

Value Percent:
Continuous Index:

Continuous Index: **S10**Within 8" of Joint: **NO**



Code: **TBI**

Description: Tap Break-in Intruding

Distance (ft): 68.3
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 11

Clock To:

 1st Value:
 6.000

 2nd Value:
 2.000

Value Percent:

Continuous Index:

Within 8" of Joint: YES

Remarks: ACTIVITY.



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 73.7
Structural Grade: 0

O&M Grade: 3

Clock Start/From: 11

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: TAP BROKEN. CAPPED. ROOTS GROWING AROUND THE CAP.



Code: DR

Description: Deformed Rigid

Distance (ft): 75.7
Structural Grade: 4
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000
Continuous Index: F09
Within 8" of Joint: NO

Remarks:



Code: RMB

Description: Roots Medium Barrel

Distance (ft): 76.0
Structural Grade: 0
O&M Grade: 4
Clock Start/From: 10
Clock To: 2
1st Value:

2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO



Code: RFL

Description: Roots Fine Lateral


Distance (ft): 76.0
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 1

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TFD**

Description: Tap Factory Defective

Distance (ft): 76.9
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 1

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: 80% PLUGGED WITH ROOTS. TAP
BROKEN. ROOTS GROWING FROM T



Code: **RFB** Description: **Roots Fine Barrel**

Distance (ft): 97.7 Structural Grade: 0 2 O&M Grade: Clock Start/From: 8 Clock To: 4 1st Value: 2nd Value: Value Percent:

Continuous Index: F10 Within 8" of Joint: NO

Remarks:



Code: FM

Description: **Fracture Multiple**

Distance (ft): 97.7 Structural Grade: 4 O&M Grade: 0 Clock Start/From: 8 Clock To: 4 1st Value: 2nd Value: Value Percent: Continuous Index: F08 Within 8" of Joint:



Code: JOMD

Description: Joint Offset Medium Defective

Distance (ft): 108.7
Structural Grade: 3
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MWLS


Description: Miscellaneous Water Level Sag

Distance (ft): 118.8
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000
Continuous Index: F07
Within 8" of Joint: NO



Code: FM
Description: Fracture Multiple

Distance (ft): 119.4
Structural Grade: 4

O&M Grade: 0

Clock Start/From: 12

Clock To: 1

1st Value: 2

2nd Value: Value Percent: 511

Continuous Index: **S11** Within 8" of Joint: **YES**

Remarks:



Code: **FM**

Description: Fracture Multiple

Distance (ft): 122.6
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 12
Clock To: 1
1st Value:
2nd Value:
Value Percent:

Continuous Index: F11
Within 8" of Joint: YES



Description: Miscellaneous Water Level Sag

Distance (ft): 122.6
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000
Continuous Index: S12
Within 8" of Joint: NO

Remarks:



Code: FH3

Description: Fracture Longitudinal Hinge, 3

Distance (ft): 131.7 Structural Grade: 4 O&M Grade: 0 Clock Start/From: 9 3 Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: YES



Code: TFC

Description: Tap Factory Capped

Distance (ft): 138.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:


1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: ROOTS GROWING AROUND THE

CAP.



Code: TF

Description: Tap Factory

Distance (ft): 141.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:


1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: ROOTS GROWING IN THE JOINTS OF

THE SERVICE.



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 144.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 12
Clock To: 3

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 153.9
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:
Value Percent:

Continuous Index: **F05**Within 8" of Joint: **YES**



Description: Miscellaneous Water Level Sag

Distance (ft): 156.4
Structural Grade: 2
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000
Continuous Index: F12
Within 8" of Joint: NO

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 156.4
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 5
Clock To: 7
1st Value:

2nd Value:

Value Percent: 5.000
Continuous Index: F04
Within 8" of Joint: YES



Code: AMH
Description: Manhole

Distance (ft): 158.0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-603-010