
Date:	10/24/2021	Weather:	Lisbort IN	Coding:	PACP 6.0
Pipe Length (ft) P.O.#:	995_2	Owner: Surveyor:	Hobart, IN M. Pielacha	Pre Clean: PSR:	Not Known P-603-019-018
Customer:	Hobart, IN	Clean Date:		Shape:	C
Street:	37th Avenue		Flow Control:		
City:	Hobart, IN		Year Renewed:		
Location:	Light Highway		Tape/Media #:	995	
Purpose:	Routine Assessment		Dia/Height:	8"	
Use:	Sanitary		Material:	VCP	
Drain Area:			Lining:		
Category:	NA				
Comment:					
Location Detail	s:		Direction of Surv	ey: Upstream	
US MH:	M-603-18	DS MH:	M-603-19	Total Length Surveyed (ft)	: 58.0
0&M Index:	2.00	O&M Quick:	2100	0 O&M Rating:	2.00
Structural Index:	0.00	– Structural Qu	uick: 0000	Structural Rating:	0.00
verall Index: 2.00		Overall Quick		Overall Rating:	2.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-603-19

Thursday, May 4, 2023




Code:	MWL
Description:	Water Level
Distance (ft):	.0
()	
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	DSF
Description:	Deposits Settled Fine
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:	50.8 0 2 4 8 10.000 S01 YES



Code: Description:	DSF Deposits Settled Fine
Distance (ft):	57.7
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	4
Clock To:	8
1st Value:	
2nd Value:	
Value Percent:	15.000
Continuous Index:	F01
Within 8" of Joint:	NO
Remarks:	



Code: Description:	MSA Abandoned Survey
Distance (ft):	58.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	deep sediment