
Profile/Pl	noto Observation	Report			RedZone
Date:	04/27/2018	Weather: Owner:	City of Hohor	Coding: t Pre Clean:	PACP 6.0
Pipe Length (f P.O.#:	115	Surveyor:	City of Hobar M. Pielacha	PSR:	No Pre-Cleaning P-603-030-031
Customer:	City of Hobart	Clean Date		Shape:	C
Street:	Cressmoor Park		Flow Control:	Not Controlle	d
City:	Hobart, IN		Year Renewed:		
Location:	Light Highway		Tape/Media #:	DEP 115	
Purpose:	Routine Assessme	nt	Dia/Height:	6"	
Use:	Sanitary		Material:	VCP	
Drain Area:			Lining:		
Category:	NA				
Comment:	YES501824 Submit	al 2			
Location Deta	ils:		Direction of Su	rvey: Downstream	
US MH:	M-603-030	DS MH:	M-603-031	Total Length Surveyed (f	t): 1.5
O&M Index:	3.00	O&M Quick	: 31	00 O&M Rating:	3.00
Structural Index	c 0.00	Structural C	uick: OC	00 Structural Rating	0.00
Overall Index:	3.00	Overall Qui	ck: 31	.00 Overall Rating:	3.00





	ode: escription:	AMH Manhole
Di	stance (ft):	.0
St	ructural Grade:	0
08	&M Grade:	0
Clo	ock Start/From:	
Clo	ock To:	
1s	t Value:	
2n	d Value:	
Va	lue Percent:	
Со	ontinuous Index:	
W	ithin 8" of Joint:	NO
Re	emarks:	M-603-030

Thursday, May 4, 2023



Code:	MWL
Description:	Water Level
Distance (ft)	0
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	DSF Deposits Settled Fine
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	5
Clock To:	7
1st Value:	
2nd Value:	
Value Percent:	15.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	MSA Abandoned Survey
Distance (ft):	1.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	sediment