Profile/Photo Observation Report



Profile/Photo Observation Report							
Date: Pipe Length (ft) P.O.#: Customer:	04/12/2018): 36-1 City of Hobart	Weather: Owner: Surveyor: Clean Date:	City of Hobai M. Pielacha	rt	J	PACP 6.0 No Pre-Cleaning M-603-037-M-603-036 C	
Street:	Off 37th Avenue	Cican Date.	Flow Control:		Not Controlled		
City:	Hobart, IN		Year Renewed	:	Not controlled		
Location:	Light Highway		Tape/Media #:	-	DEP 36		
Purpose:	Routine Assessment		Dia/Height:		6"		
Use:	Sanitary		Material:		VCP		
Drain Area:			Lining:				
Category:	NA						
Comment:							
Location Detail	S:		Direction of Su	ırvey:	Upstream		
US MH:	M-603-037	DS MH:	M-603-036	To	otal Length Surveyed (ft):	2.1	
O&M Index:	0.00	O&M Quick:	00	000	O&M Rating:	0.00	
Structural Index:	0.00	Structural Q		000	Structural Rating:	0.00	
Overall Index:	0.00	Overall Quic		000	Overall Rating:	0.00	
	-	_ ,	-				

Thursday, May 4, 2023 1

Pos	sition	Code	Observation	Video (sec)	Grade
M(603-)036					
0.	A	AMH	Manhole	0	NA
\.0	1	MWL	Water Level	8	NA
2.1	. ſ	MSA	Abandoned Survey	112	NA
Camera Direction					

Code:



Description: Manhole Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: NO Remarks: M-603-036

AMH

Thursday, May 4, 2023 2



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:


Continuous Index:

Within 8" of Joint: NO

Code:

10.000

Remarks:



MSA

Description: **Abandoned Survey**

Distance (ft): 2.1 Structural Grade: 0 O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: sediment

3 Thursday, May 4, 2023