
Profile/Ph	oto Observatio	n Report				RedZone	
Date:	04/23/2018	Weather:			Coding:	PACP 6.0	
Pipe Length (ft	): <b>316.8</b>	Owner:	NA		Pre Clean:	Not Known	
P.O.#:		Surveyor:	Jen Costel	lo	PSR:	P-604-005-004	
Customer:		Clean Date	e: 01/01/190	00	Shape:	С	
Street: W CLEVELAND AVE & WILLOW PL		Flow Contro	Flow Control:				
City:	Hobart, IN		Year Renew	ed:			
Location:	Other		Tape/Media	n #:			
Purpose:	Not Known		Dia/Height:		8"		
Use:	Sanitary		Material:		PVC		
Drain Area:	NA		Lining:				
Category:	NA						
Comment:							
Location Detail	ls:		Direction of	Survey:	Upstream		
US MH:	M-604-004	DS MH:	M-604-005	To	tal Length Surveyed (ft)	5 <b>.2</b>	
0&M Index:	2.00	O&M Quick	::	2100	O&M Rating:	2.00	
tructural Index:	0.00	Structural C	Quick:	0000	Structural Rating:	0.00	
Overall Index:	2.00	Overall Qui	ck:	2100	Overall Rating:	2.00	





Code: Description:	AMH Manhole
Description	Manifold
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-604-005



Code: MWL Description: Water Level

.0
0
0
5.000
NO



Code:	TFA
Description:	<b>Tap Factory Active</b>
Distance (ft)	0
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: Description:	OBZ Obstacle Other
Distance (ft):	1.4
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	6
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO

stick


MSA

Abandoned Survey

Remarks:

Code:

Description:



Distance (ft):	4.9			
Structural Grade:	0			
O&M Grade:	0			
Clock Start/From:				
Clock To:				
1st Value:				
2nd Value:				
Value Percent:				
Continuous Index:				
Within 8" of Joint:	NO			
Remarks:	stick			