
Date:	04/23/2018	Weather:			Coding:	PACP 6.0
Pipe Length (ft)	: 200.2	Owner:	NA		Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello		PSR:	P-604-009-008
Customer:		Clean Date:	01/01/1900		Shape:	С
Street:	BEVERLY BLVD		Flow Control:		Not Controlled	
City:	Hobart, IN		Year Renewed:			
Location:	Other		Tape/Media #:			
Purpose:	Not Known		Dia/Height:		8"	
Use:	Sanitary		Material:		VCP	
Drain Area:	NA		Lining:			
Category:	NA					
Comment:						
Location Details	s:		Direction of Surv	vey:	Downstream	
US MH:	M-604-008	DS MH:	M-604-009	Total Len	gth Surveyed (ft)	: 34.5
D&M Index:	1.75	O&M Quick:	231	. 1 (0&M Rating:	7.00
Structural Index:	2.89	Structural Qu	uick: 413	_	tructural Rating:	26.00
Overall Index:	2.54	Overall Quick		_	Verall Rating:	33.00

	Position	Code	Observation	Video (sec)	Grade
M(604	008				
	.0	AMH	Manhole	10	NA
	.0	MWL	Water Level	20	NA
	.0	ММС	Material Change	31	NA
	<u>0</u>	SAP(S01)	Surface Aggregate Projecting	41	S 3
	4.1	LR	Alignment Right	60	M 1
	4.1	JOM	Joint Offset Medium	71	S 1
	12.4	MWL	Water Level	99	NA
	/ 16.2	FM	Fracture Multiple	117	S 4
_	_/ /28.2	IW	Infil Weeper	152	M 2
5	34.5	IW	Infil Weeper	176	M 2
ecti	34.5	DAE	Deposits Attached Encrustation	186	M 2
Camera Direction		SAP(F01)	Surface Aggregate Projecting	197	S 3
nera	34.5	MSA	Abandoned Survey	207	NA
M (604	1 , 009				



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-604-008



Code: MWL Description: Water Level

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: 5.000 Continuous Index: Within 8" of Joint: NO Remarks:



Code: Description:	MMC Material Change
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	ср



Code:SAPDescription:Surface Aggregate Projecting

Distance (ft):	.0
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	S01
Within 8" of Joint:	
Remarks:	



LR Alignment Right
4.1
0
1
5.000
NO



Code:JOMDescription:Joint Offset Medium

Distance (ft):	4.1
Structural Grade:	1
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	MWL
Description:	Water Level
Distance (ft):	12.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	30.000
Continuous Index:	

NO


Within 8" of Joint:

Remarks:



Code: Description:	FM Fracture Multiple
Distance (ft):	16.2
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES

Remarks:



Code: Description:	IW Infil Weeper
Distance (ft): Structural Grade: O&M Grade: Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: Remarks:	28.2 0 2 8 4 YES



Code: Description:	IW Infil Weeper
Description.	inin weeper
Distance (ft):	34.5
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	9
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES

Remarks:



Code:	DAE
Description:	Deposits Attached Encrustation

Distance (ft):	34.5
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	7
Clock To:	9
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:SAPDescription:Surface Aggregate Projecting

Distance (ft):	34.5
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	F01
Within 8" of Joint:	
Remarks:	



Code:	MSA
Description:	Abandoned Survey

Distance (ft):	34.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	unknown