Date:	04/12/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft)	: 82.0	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello	PSR:	P-604-040-039
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	W 40th ave		Flow Control:	Not Controlled	
City:	Hobart, IN		Year Renewed:		
Location:	Other		Tape/Media #:		
Purpose:	Not Known		Dia/Height:	12"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Details	5:		Direction of Surve	ey: Downstream	
US MH:	M-604-039	DS MH:	M-604-040	Total Length Surveyed (ft)	: 77.0
D&M Index:	2.25	O&M Quick:	3221	O&M Rating:	9.00
Structural Index:	3.67	Structural Qu	(22)		11.00
Overall Index:	2.86	Overall Quicl	(22)		20.00

	Position	Code	Observation	Video (sec)	Grade
M(604-0)39				
\sim	0.	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
	5.6	RMJ	Roots Medium Joint	44	M 3
	16.1	MWL	Water Level	76	NA
	34.7	MWL	Water Level	125	NA
	46.6	FM	Fracture Multiple	160	S 4
	53.3	RFJ	Roots Fine Joint	184	M 1
	70.9	FL	Fracture Longitudinal	231	S 3
	70.9	В	Broken	242	S 4
5	70.9	DSGV	Deposits Settled Gravel	254	M 3
	72.9	OBR	Obstacle Rocks	269	M 2
ā	77.0	AMH	Manhole	289	NA
Camera Direction					
M(604)	040				




Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-604-039



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	RMJ
Description:	Roots Medium Joint

Distance (ft):	5.6
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	1
Clock To:	2
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code:	MWL
Description:	Water Level

Distance (ft):	16.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	30.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	


Continuous Index: Within 8" of Joint:

Remarks:



Code:	MWL
Description:	Water Level
Distance (ft):	34.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000

NO



Code:FMDescription:Fracture Multiple

Distance (ft):	46.6
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	7
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	RFJ
Description:	Roots Fine Joint
Distance (ft):	F2 2
Distance (ft):	53.3
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	4
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES

Remarks:



Code:FLDescription:Fracture Longitudinal

Distance (ft):	70.9
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	12
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	B Broken
Distance (ft):	70.9
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	12
Clock To:	1
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:DSGVDescription:Deposits Settled Gravel

Distance (ft):	70.9
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	4
Clock To:	8
1st Value:	
2nd Value:	
Value Percent:	20.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	OBR
Description:	Obstacle Rocks
Distance (ft):	72.9
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	6
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	AMH
Description:	Manhole

Distance (ft):	77.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-604-040