## **Profile/Photo Observation Report**



Date: 04/23/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 178.2 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-604-042-050 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: Summerlin Flow Control: Not Controlled

City: Hobart, IN Year Renewed:

Purpose: Not Known Dia/Height: 12"
Use: Sanitary Material: PVC

Drain Area: NA Lining:

Category: NA

**Light Highway** 

Location:

Comment:

Location Details: Direction of Survey: Downstream

US MH: M-604-050 DS MH: M-604-042 Total Length Surveyed (ft): 173.4

2.00 2100 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2100 2.00 Overall Rating: Overall Index: Overall Quick:

Tape/Media #:

	Position	Code	Observation	Video (sec)	Grade
604	050				
	0. //	AMH	Manhole	10	NA
ш	0.	MWL	Water Level	21	NA
ш	32.8	OBZ	Obstacle Other	98	M 2
ш	/35.1	TFA	Tap Factory Active	116	NA
	48.9	MGO	General Observation	159	NA
ш	84.5	TFA	Tap Factory Active	242	NA
Ш	90.7	TFA	Tap Factory Active	267	NA
ш	134.2	TF	Tap Factory	365	NA
ш	171.3	TF	Tap Factory	451	NA
ш	173.4	AMH	Manhole	468	NA
H					

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:  O&M Grade:  Clock Start/From:	0 0
Clock To:  1st Value:	
2nd Value: Value Percent:	
Continuous Index: Within 8" of Joint: Remarks:	NO M-604-050

**AMH** 



Code: MWL
Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

Code: OBZ

Description: Obstacle Other

NO




Distance (ft): 32.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 6
Clock To: 8

1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO Remarks: misc



Code: TFA

Description: Tap Factory Active

Distance (ft): 35.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:


1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Description: General Observation



Distance (ft): 48.9
Structural Grade: 0


O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: rear camera



Code: TFA

Description: Tap Factory Active

Distance (ft): 84.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

Remarks:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: TFA

Description: Tap Factory Active

Distance (ft): 90.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 9

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF** 

Description: Tap Factory

Distance (ft): 134.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF** 

Description: Tap Factory

Distance (ft): 171.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 3

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 173.4
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-604-042