Profile/Ph	noto Observation	Report			RedZo
Date:	04/24/2018	Weather:		Coding:	PACP 6.0
Pipe Length (f	t): 222.5	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello	PSR:	P-604-066-065
Customer:		Clean Date:	01/01/1900	Shape:	С
Street:	S Pennsylvania St.		Flow Control:	Not Controlle	ed
City:	Hobart, IN		Year Renewed:		
Location:	Other		Tape/Media #:		
Purpose:	Not Known		Dia/Height:	12"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Detai	ils:		Direction of Sur	vey: Downstream	
US MH:	M-604-066	DS MH:	M-604-065	Total Length Surveyed (ft): 216.4
D&M Index:	0.00	O&M Quick:	00	00 O&M Rating:	0.00
Structural Index	3.28	Structural Qu	uick: 4A	_	g: 82.00
Overall Index:	3.28	Overall Quick			82.00

	Position	Code	Observation	Video (sec)	Grade
A 604-0	66				
	.0	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
	2.6	TF	Tap Factory	40	NA
	4.8	TFA	Tap Factory Active	59	NA
	21.4	FC	Fracture Circumferential	106	S 2
<u> </u>	36.0	FL	Fracture Longitudinal	147	S 3
	43.7	TF	Tap Factory	176	NA
	44.8	FL	Fracture Longitudinal	191	S 3
	45.9	TF	Tap Factory	207	NA
5	48.6	FM(S01)	Fracture Multiple	226	S 4
	83.1	TF	Tap Factory	309	NA
Lamera Direction	85.0	TFA	Tap Factory Active	327	NA
	100.3	FM(F01)	Fracture Multiple	371	S 4
	/ 122.5	TF	Tap Factory	429	NA
∎ /	/ 124.2	TF	Tap Factory	447	NA
	// 132.2	CL	Crack Longitudinal	477	S 2
	/139.6	FL(S02)	Fracture Longitudinal	503	S 3
	//156.0	FL(F02)	Fracture Longitudinal	548	S 3
	/156.0	FL	Fracture Longitudinal	559	S 3
//	161.8	TF	Tap Factory	583	NA
	/ 162.4	FS	Fracture Spiral	597	S 3
	// 163.7	TF	Tap Factory	613	NA
	/ 166.2	CL	Crack Longitudinal	632	S 2
	/ 190.0	FM	Fracture Multiple	691	S 4
	/196.4	CL	Crack Longitudinal	716	S 2
	//197.9	TF	Tap Factory	733	NA
	// 198.5	FL	Fracture Longitudinal	747	S 3
	/ 199.9	TFA	Tap Factory Active	763	NA
	206.7	CL	Crack Longitudinal	791	S 2
	212.7	FM	Fracture Multiple	815	S 4
	216.4	AMH	Manhole	833	NA




Code:AMHDescription:Manhole

.0
0
0
NO
M-604-066

Code:

Description:



Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	

MWL

Water Level



Code:	TF
Description:	Tap Factory

Distance (ft):	2.6
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: Description:	TFA Tap Factory Active
Distance (ft):	4.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:FCDescription:Fracture Circumferential

Distance (ft):	21.4
Structural Grade:	2
O&M Grade:	0
Clock Start/From:	9
Clock To:	12
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	FL Fracture Longitudinal
Distance (ft):	36.0
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES




Code:	TF
Description:	Tap Factory

Distance (ft):	43.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code:	FL
Description:	Fracture Longitudinal

Distance (ft):	44.8
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	TF
Description:	Tap Factory

Distance (ft):	45.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	2
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	FM
Description:	Fracture Multiple
Distance (ft):	48.6
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	8
Clock To:	4
1st Value:	
2 m d Maluar	

2nd Value: Value Percent: Continuous Index: **S01** Within 8" of Joint: **YES** Remarks:



Code:	TF
Description:	Tap Factory

Distance (ft):	83.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	

Continuous Index: Within 8" of Joint:



Code:	TFA
Description:	Tap Factory Active
Distance (ft):	85.0
()	-
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	



Code:FMDescription:Fracture Multiple

Distance (ft):	100.3
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	F01
Within 8" of Joint:	YES
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	122.5
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	TF
Description:	Tap Factory

Distance (ft):	124.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	CL
Description:	Crack Longitudinal
	/ •• •
Distance (ft):	132.2
Structural Grade:	2
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	



Code:FLDescription:Fracture Longitudinal

Distance (ft):	139.6
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	12
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	S02
Within 8" of Joint:	YES
Remarks:	

Code:

Description:



Distance (ft):	156.0
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	12
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	F02
Within 8" of Joint:	YES
Remarks:	

FL

Fracture Longitudinal



Code:FLDescription:Fracture Longitudinal

Distance (ft):	156.0
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	161.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	




Code:FSDescription:Fracture Spiral

Distance (ft):	162.4
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	3
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	163.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: CL Description: Crack Longitudinal

Distance (ft): 166.2 Structural Grade: 2 O&M Grade: 0 Clock Start/From: 1 Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint: YES Remarks:

Code:

Description:	Fracture Multiple
Distance (ft):	190.0
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	

FM

Value Percent: Continuous Index: Within 8" of Joint: YES Remarks:



Code: CL Description: Cra

CL Crack Longitudinal

Distance (ft):	196.4
Structural Grade:	2
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	197.9
Structural Grade: O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:FLDescription:Fracture Longitudinal

Distance (ft):	198.5
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	2
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	TFA
Description:	Tap Factory Active
Distance (ft):	199.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	

Within 8" of Joint:




Code: CL Description: Crac

CL Crack Longitudinal

Distance (ft):	206.7
Structural Grade:	2
O&M Grade:	0
Clock Start/From:	8
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	FM Fracture Multiple
Distance (ft):	212.7
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	AMH
Description:	Manhole

Distance (ft):	216.4
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-604-065