Profile/Ph	oto Observatio	n Report			RedZor
Date:	04/24/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft	z): 229.8	Owner:	NA	Pre Clean:	Not Known
P.O.#:		Surveyor:	Jen Costello	PSR:	P-604-067-066
Customer:		Clean Date:	01/01/1900	Shape:	C
Street:	N PENNSYLVANIA	A ST & W HOME A	V Flow Control:	Not Control	ed
City:	Hobart, IN		Year Renewed:		
Location:	Other		Tape/Media #:		
Purpose:	Not Known		Dia/Height:	12"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Detai	ls:		Direction of Su	rvey: Downstrean	า
US MH:	M-604-067	DS MH:	M-604-066	Total Length Surveyed	(ft): 227.3
D&M Index:	1.64	O&M Quick:	31	.25 O&M Rating:	18.00
Structural Index	3.68	Structural Q	45	Structural Ratir	ng: 114.00
Overall Index:	3.14	Overall Quic		Overall Rating:	132.00

	Position	Code	Observation	Video (sec)	Grade
M(604-)	067				
	0.	AMH	Manhole	10	NA
	.0	MWL	Water Level	22	NA
	<u>\\.0</u>	FC	Fracture Circumferential	33	S 2
	13.9	CL	Crack Longitudinal	72	S 2
	1 18.1	FM	Fracture Multiple	92	S 4
	1	FM	Fracture Multiple	109	S 4
	29.0	SSS	Surface Spalling	138	S 2
	√ \ <u>35.0</u>	FM	Fracture Multiple	162	S 4
	49.5	RFJ(S01)	Roots Fine Joint	203	M 1
5 	60.2	RMJ	Roots Medium Joint	236	M 3
	69.8	TF	Tap Factory	268	NA
Camera Direction	71.3	FL	Fracture Longitudinal	287	S 3
	71.3	RFJ(F01)	Roots Fine Joint	300	M 1
E I	72.2	TFA	Tap Factory Active	315	NA
	$\sqrt{83.1}$	FM	Fracture Multiple	351	S 4
	95.5	FM	Fracture Multiple	388	S 4
Ļ	111.9	TF	Tap Factory	434	NA
	111.9	СМ	Crack Multiple	445	S 3
	114.3	TFA	Tap Factory Active	466	NA
	\\\114.3	MGO	General Observation	477	NA
	$\sqrt{124.3}$	FM(S02)	Fracture Multiple	509	S 4
	137.1	DAE(S03)	Deposits Attached Encrustation	546	M 2
	145.5	DAE(F03)	Deposits Attached Encrustation	574	M 2
	149.1	SSS	Surface Spalling	593	S 2
	152.1	TFC	Tap Factory Capped	611	NA
	152.1	DAE	Deposits Attached Encrustation	622	M 2
	154.2	TF	Tap Factory	638	NA
	160.2	DAE	Deposits Attached Encrustation	662	M 2
	189.3	DAE	Deposits Attached Encrustation	731	M 2
	191.7	TF	Tap Factory	748	NA
	193.4	RFJ	Roots Fine Joint	763	M 1
	194.3	TFA	Tap Factory Active	777	NA
	225.1	FM(F02)	Fracture Multiple	852	S 4
	227.3	AMH	Manhole	872	NA



Code:	AMH
Description:	Manhole

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-604-067

Code:



Description:	Water Level
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	

MWL



Code:FCDescription:Fracture Circumferential

Distance (ft):	.0
Structural Grade:	2
O&M Grade:	0
Clock Start/From:	1
Clock To:	3
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	

Remarks:




Code: Description:	CL Crack Longitudinal
Distance (ft):	13.9
Structural Grade:	2
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES



Code:FMDescription:Fracture Multiple

Distance (ft):	18.1
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	FM Fracture Multiple
Distance (ft):	20.3
Structural Grade:	4
O&M Grade: Clock Start/From:	0 10
Clock To:	2
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	SSS
Description:	Surface Spalling

Distance (ft):	29.0
Structural Grade:	2
O&M Grade:	0
Clock Start/From:	3
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	FM Fracture Multiple
Distance (ft):	35.0
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	9
Clock To:	11
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	RFJ
Description:	Roots Fine Joint

Distance (ft):	49.5
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	S01
Within 8" of Joint:	YES
Remarks:	



Code:	RMJ
Description:	Roots Medium Joint

Distance (ft):	60.2
Structural Grade:	0
O&M Grade:	3
Clock Start/From:	10
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code:	TF
Description:	Tap Factory

Distance (ft):	69.8
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: Description:	FL Fracture Longitudinal
Distance (ft):	71.3
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	1
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	




Code:	RFJ
Description:	Roots Fine Joint

Distance (ft):	71.3
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	F01
Within 8" of Joint:	YES
Remarks:	



Code:	TFA
Description:	Tap Factory Active
Distance (ft):	72.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	2
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code: FM Description: Fracture Multiple

Distance (ft):	83.1	
Structural Grade:	4	
O&M Grade:	0	
Clock Start/From:	9	
Clock To:	11	
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	YES	
Remarks:		



Code: Description:	FM Fracture Multiple
Distance (ft):	95.5
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	10
Clock To:	2
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	TF
Description:	Tap Factory

Distance (ft):	111.9
Distance (ft):	111.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	СМ
Description:	Crack Multiple
(4)	
Distance (ft):	111.9
Structural Grade:	3
O&M Grade:	0
Clock Start/From:	3
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES

Remarks:



Code:TFADescription:Tap Factory Active

Distance (ft):	114.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	2
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	MGO
Description:	General Observation

Distance (ft):	114.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	rear camera



Code:FMDescription:Fracture Multiple

Distance (ft):	124.3
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	S02
Within 8" of Joint:	YES
Remarks:	

Code:



Description:	Deposits Attached Encrustation
Distance (ft): Structural Grade:	137.1 0
O&M Grade:	2


DAE

O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	S03
Within 8" of Joint:	YES
Remarks:	




Code:DAEDescription:Deposits Attached Encrustation

Distance (ft):	145.5
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	F03
Within 8" of Joint:	YES
Remarks:	



Code:	SSS
Description:	Surface Spalling

Distance (ft):	149.1
Structural Grade:	2
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:TFCDescription:Tap Factory Capped

Distance (ft):	152.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	dae

Code:

Description:

152.1
0
2
7
9
5.000
NO

DAE

Deposits Attached Encrustation



Code:	TF
Description:	Tap Factory

Distance (ft):	154.2
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	3
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	DAE
Description:	Deposits Attached Encrustation

Distance (ft):	160.2
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	9
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:DAEDescription:Deposits Attached Encrustation

Distance (ft):	189.3
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	191.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	9
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:RFJDescription:Roots Fine Joint

Distance (ft):	193.4
Structural Grade:	0
O&M Grade:	1
Clock Start/From:	11
Clock To:	1
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	TFA
Description:	Tap Factory Active
Distance (ft):	194.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	2
Clock To:	

	_
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:FMDescription:Fracture Multiple

Distance (ft):	225.1
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	F02
Within 8" of Joint:	YES
Remarks:	



Code:	AMH
Description:	Manhole

Distance (ft):	227.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-604-066