Profile/Photo Observation Report



Date: 04/20/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 219.2 Owner: NA Pre Clean: **Not Known** P.O.#: **Byrd Fitzgerald** PSR: P-604-075-074 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: Summerlin Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Not Known Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:


Location Details: Direction of Survey: Downstream

US MH: M-604-075 DS MH: M-604-074 Total Length Surveyed (ft): 59.2

2.22 20.00 O&M Index: O&M Quick: O&M Rating: 2.86 3621 20.00 Structural Quick: Structural Rating: Structural Index: 40.00 2.50 Overall Quick: Overall Rating: Overall Index:


	Position	Code	Observation	Video (sec)	Grade
604	075				
	0.	AMH	Manhole	10	NA
ш	\\.0	MWL	Water Level	21	NA
ш	2.5	CL	Crack Longitudinal	38	S 2
ш	18.3	DAE	Deposits Attached Encrustation	81	M 2
ш	21.9	DAE(S01)	Deposits Attached Encrustation	99	M 2
ш	30.9	CM(S02)	Crack Multiple	129	S 3
ш	// 53.1	RMB(S03)	Roots Medium Barrel	185	M 4
Н	59.2	MSA	Abandoned Survey	208	NA
	59.2	RMB(F03)	Roots Medium Barrel	220	M 4
	59.2	CM(F02)	Crack Multiple	231	S 3
ш	59.2	DAE(F01)	Deposits Attached Encrustation	242	M 2
Ш					

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-604-075		

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

Code:

5.000

NO

CL

Description: **Crack Longitudinal**



Distance (ft): 2.5 Structural Grade: 2

O&M Grade: 0 Clock Start/From: 3

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks: minor



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 18.3
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 11

1st Value: 2nd Value:

Value Percent: 5.000


Continuous Index:

Within 8" of Joint:

Remarks:

2nd Value:

YES



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 21.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 12
1st Value:

Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: YES

Remarks: wandering



Code: CM

Description: Crack Multiple

Distance (ft): 30.9
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value: Value Percent:

Continuous Index: S02
Within 8" of Joint: YES

Remarks: wandering



Code: RMB

Description: Roots Medium Barrel

Distance (ft): 53.1
Structural Grade: 0

O&M Grade: 4

Clock Start/From: 6

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000
Continuous Index: S03
Within 8" of Joint: NO

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 59.2
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: rmb

Code: RMB

Description: Roots Medium Barrel

Distance (ft): 59.2
Structural Grade: 0
O&M Grade: 4
Clock Start/From: 6

Clock To: 1st Value: 2nd Value:

Value Percent: 20.000
Continuous Index: F03
Within 8" of Joint: NO

Remarks:



Code: CM


Description: Crack Multiple

Distance (ft): 59.2
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 7
Clock To: 5

1st Value: 2nd Value: Value Percent:

Continuous Index: F02
Within 8" of Joint: YES

Remarks: wandering



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 59.2
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 7

Clock To: 12

1st Value:

2nd Value: Value Percent:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: YES

Remarks: wandering