Profile/Photo Observation Report



Date: 04/22/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 186.2 Owner: NA Pre Clean: **Not Known** P.O.#: **Brandon Helbling** PSR: P-604-092-091 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: Summerlin Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Light Highway Tape/Media #:

Purpose: Not Known Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA
Comment:

Location Details: Direction of Survey: **Downstream**

US MH: M-604-091 DS MH: M-604-092 Total Length Surveyed (ft): 43.7

1.00 1200 2.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 1.00 1200 2.00 Overall Index: Overall Quick: Overall Rating:

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-604-091

 AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:


Continuous Index:

Within 8" of Joint:

Remarks:

10.000

NO




Code: MMC

Description: **Material Change**

Distance (ft): 5.1 Structural Grade: 0 O&M Grade: 0 Clock Start/From: Clock To: 1st Value: 2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: PVC



Code: MMC

Description: Material Change

Distance (ft): 12.5
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: VCP



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 14.3
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 7
Clock To: 5
1st Value:
2nd Value:
Value Percent:

Continuous Index: **S01** Within 8" of Joint: **YES**

Remarks:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 22.1
Structural Grade: 0

O&M Grade: 1


Clock Start/From: 7

Clock To: 5

1st Value: 2nd Value: Value Percent:

Continuous Index: F01
Within 8" of Joint: YES

Remarks:



Code: MMC

Description: Material Change


Distance (ft): 23.0 Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO Remarks: PVC



Code: **TF**

Description: Tap Factory


Distance (ft): 24.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 26.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 10

Clock To:

2nd Value:

1st Value: **4.000**

Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: MMC

Description: Material Change

Distance (ft): 30.5
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: VCP



Code: MSA

Description: Abandoned Survey

Distance (ft): 43.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: No blockage