## **Profile/Photo Observation Report**



Date: 04/24/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 173.4 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-604-108-111 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: N Ash St, Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: **Downstream** 

US MH: M-604-111 DS MH: M-604-108 Total Length Surveyed (ft): 25.7

2.50 5.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.50 5.00 Overall Quick: Overall Rating: Overall Index:

	Position	Code	Observation	Video (sec)	Grade
504-111	L				
7.	.0	AMH	Manhole	11	NA
	.0	MWL	Water Level	22	NA
<del></del> -\	2.6	RFJ	Roots Fine Joint	39	M 1
	25.7	MWL	Water Level	97	NA
	25.7	MCU	Camera Underwater	108	M 4
	25.7	MSA	Abandoned Survey	120	NA
Ш					

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-604-111		

**AMH** 



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To:

1st Value: 2nd Value:

Value Percent: 40.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO

Code: RFJ

Description: **Roots Fine Joint** 



Distance (ft): 2.6 Structural Grade: 0 O&M Grade:

1 Clock Start/From: 8 Clock To: 4

1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: MWL

Description: Water Level

Distance (ft): 25.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

100.000

NO

Code: MCU

Description: Camera Underwater



Distance (ft): 25.7 Structural Grade: 0

O&M Grade: 4

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 25.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO Remarks: mcu