Profile/Photo Observation Report



Date: 04/25/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 165.1 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-605-075-008 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: S ASH ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA
Comment: Flow direction wrong. Debris at 8'.

Location Details: Direction of Survey: **Upstream**

US MH: M-605-008 DS MH: M-605-075 Total Length Surveyed (ft): 10.4

2.17 3321 13.00 O&M Index: O&M Quick: O&M Rating: 3.33 10.00 Structural Quick: Structural Rating: Structural Index: 2.56 23.00 Overall Quick: Overall Rating: Overall Index:

Position	Code	Observation	Video (sec)	Grade
605-075				
0.	AMH	Manhole	10	NA
.0	MWL	Water Level	21	NA
0.	FC	Fracture Circumferential	33	S 2
0.	RMJ	Roots Medium Joint	45	M 3
2.8	RMJ	Roots Medium Joint	61	M 3
4.9	FM	Fracture Multiple	76	S 4
4.9	RMJ	Roots Medium Joint	87	M 3
6.8	RFJ	Roots Fine Joint	101	M 1
8.8	FM	Fracture Multiple	116	S 4
8.8	RFJ	Roots Fine Joint	126	M 1
8.8	DAZ	Deposits Attached Other	136	M 2
10.4	MSA	Abandoned Survey	150	NA

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-605-075		

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0
Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

5.000

NO

Code: FC

Description: Fracture Circumferential



Distance (ft): .0
Structural Grade: 2

Structural Grade: 2

O&M Grade: 0

Clock Start/From: 7

Clock To:
1st Value:
2nd Value:
Value Percent:

Continuous Index:

Within 8" of Joint:

Remarks:

YES

11



Code: RMJ

Description: Roots Medium Joint

Distance (ft): .0
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 1
Clock To: 4
1st Value:

2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 2.8
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:

Value Percent: 15.000

Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: FM

Description: Fracture Multiple

Distance (ft): 4.9
Structural Grade: 4

O&M Grade: 0
Clock Start/From: 8

Clock To: 4

1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: RMJ

Description: Roots Medium Joint

Distance (ft): 4.9
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 2
Clock To: 4
1st Value:
2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 6.8
Structural Grade: 0

O&M Grade: 1

Clock Start/From: 8

Clock To: 4

1st Value: 2nd Value: Value Percent:

Within 8" of Joint:

Continuous Index:

Remarks:

Code: FM

Description: Fracture Multiple

YES



Distance (ft): 8.8
Structural Grade: 4
O&M Grade: 0

Clock Start/From: 12
Clock To: 4

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 8.8
Structural Grade: 0
O&M Grade: 1
Clock Start/From: 12

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAZ

Description: Deposits Attached Other

Distance (ft): 8.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 9
1st Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: YES

Remarks:

2nd Value:



Code: MSA

Description: Abandoned Survey

Distance (ft): 10.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO Remarks: roots