## **Profile/Photo Observation Report**



Date: 04/25/2018 Weather: **PACP 6.0** Coding: Pipe Length (ft): 247.1 Owner: NA Pre Clean: **Not Known** P.O.#: Jen Costello PSR: P-605-026-025 Surveyor:

Customer: Clean Date: 01/01/1900 Shape: C

Street: S ASH ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Other Tape/Media #:

Purpose: Not Known Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: NA Lining: Category: NA

Comment: Flow direction wrong.

Location Details: Direction of Survey: **Downstream** 

US MH: M-605-025 DS MH: M-605-026 Total Length Surveyed (ft): 248.5

2.00 312C 46.00 O&M Index: O&M Quick: O&M Rating: 3.89 514F 171.00 Structural Quick: Structural Rating: Structural Index: 3.24 217.00 514F Overall Quick: Overall Rating: Overall Index:

P	osition	Code	Observation	Video (sec)	Grade
05-025					
0.	)	AMH	Manhole	10	NA
\\\_0	1	MWL	Water Level	21	NA
\\\.0	1	FM	Fracture Multiple	32	S 4
$\sqrt{12}$	2.5	TFA	Tap Factory Active	69	NA
$-\sqrt{\frac{1}{27}}$	7.4	FM	Fracture Multiple	111	S 4
\\_31	1.6	DAE	Deposits Attached Encrustation	131	M 2
<u> </u>	2.3	FM	Fracture Multiple	164	S 4
<b>₹</b> \\\\ 46	5.2	FL	Fracture Longitudinal	184	S 3
\\\ <u>47</u>	7.8	TF	Tap Factory	199	NA
\	2.5	FM	Fracture Multiple	221	S 4
\\\\ <u>_</u>	3.7	TF	Tap Factory	235	NA
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	4.4	ID	Infil Dripper	248	M 3
\\\\ <u>\</u> 68	3.9	FM	Fracture Multiple	288	S 4
\\\\ <u>7</u>	5.1	FL	Fracture Longitudinal	312	S 3
\\\ <u>7</u> 8	3.9	FM(S01)	Fracture Multiple	332	S 4
\\ <u>7</u> 8	3.9	DAE(S02)	Deposits Attached Encrustation	343	M 2
\ <u>9</u> 2	2.9	TF	Tap Factory	383	NA
13	32.3	TF	Tap Factory	474	NA
13	34.2	TF	Tap Factory	489	NA
15	57.0	TF	Tap Factory	547	NA
16	52.6	DAE(F02)	Deposits Attached Encrustation	570	M 2
	75.3	TF	Tap Factory	607	NA
/19	96.5	SSS	Surface Spalling	660	S 2
<u> </u>	01.9	TF	Tap Factory	683	NA
//21	14.1	TFD	Tap Factory Defective	719	M 2
///21	14.1	DAE	Deposits Attached Encrustation	731	M 2
<u> </u>	16.7	TBI	Tap Break-in Intruding	747	M 2
	16.7	BVV	Broken Void Visible	759	S 5
	21.1	SSS	Surface Spalling	780	S 2
	38.3	TFA	Tap Factory Active	826	NA
/24	41.4	RFJ	Roots Fine Joint	844	M 1
// 24	46.9	FM(F01)	Fracture Multiple	867	S 4
$-\frac{1}{2^{2}}$	48.5	AMH	Manhole	881	NA



Code: AMH
Description: Manhole

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-605-025



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From: Clock To:

1st Value: 2nd Value:

Value Percent: 20.000

Continuous Index:

Within 8" of Joint: NO



Description: Fracture Multiple


Distance (ft): .0
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 8
Clock To: 9
1st Value:
2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: TFA

Description: Tap Factory Active

Distance (ft): 12.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Description: Fracture Multiple

Distance (ft): 27.4
Structural Grade: 4

O&M Grade: 0
Clock Start/From: 12
Clock To: 4

1st Value:
2nd Value:
Value Percent:

Continuous Index: Within 8" of Joint:

Remarks:

YES



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 31.6
Structural Grade: 0

O&M Grade: 2

Clock Start/From: 1

Clock To: 4

1st Value: 2

2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES



Description: Fracture Multiple

Distance (ft): 42.3
Structural Grade: 4

O&M Grade: 0

Clock Start/From: 8

Clock To: 4

1st Value:
2nd Value:
Value Percent:

Continuous Index: Within 8" of Joint:

Remarks:

YES



Code: FL

Description: Fracture Longitudinal

Distance (ft): 46.2
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 9
Clock To:
1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: TF

Description: **Tap Factory** 

Distance (ft): 47.8 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 11

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: FΜ

Description: **Fracture Multiple** 

YES

Distance (ft): 52.5 Structural Grade: 4 O&M Grade: 0 Clock Start/From: 2 4 Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:



Code: **TF** 

Description: Tap Factory

Distance (ft): 53.7
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: ID

Description: Infil Dripper

Distance (ft): 54.4
Structural Grade: 0

O&M Grade: 3

Clock Start/From: 12

Clock To:
1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Description: Fracture Multiple

Distance (ft): 68.9
Structural Grade: 4

O&M Grade: 0

Clock Start/From: 11

Clock To: 12

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: FL

Description: Fracture Longitudinal

Distance (ft): 75.1
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 12
Clock To:

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Description: Fracture Multiple

Distance (ft): 78.9
Structural Grade: 4

O&M Grade: 0

Clock Start/From: 8

Clock To: 4

1st Value:
2nd Value:

Value Percent:
Continuous Index: S01
Within 8" of Joint: YES

Remarks:

Code: DAE

Description: Deposits Attached Encrustation



Distance (ft): 78.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:

Value Percent: 5.000
Continuous Index: S02
Within 8" of Joint: YES

Remarks:

2nd Value:



Code: **TF** 

Description: Tap Factory


Distance (ft): 92.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF** 


Description: Tap Factory

Distance (ft): 132.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 1

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TF** 

Description: Tap Factory

Distance (ft): 134.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF** 

Description: Tap Factory

Distance (ft): 157.0
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 11

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 162.6
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:

Value Percent: 5.000
Continuous Index: F02
Within 8" of Joint: YES

Remarks:

2nd Value:

Code: **TF** 

Description: Tap Factory



Distance (ft): 175.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: SSS

Description: Surface Spalling

Distance (ft): 196.5
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 1
Clock To: 3

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TF** 

Description: Tap Factory

Distance (ft): 201.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: **TFD** 

Description: Tap Factory Defective

Distance (ft): 214.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks: dae



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 214.1
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 1
Clock To: 4
1st Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

2nd Value:



Code: TBI

Description: Tap Break-in Intruding

Distance (ft): 216.7
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 2

Clock To:

 1st Value:
 4.000

 2nd Value:
 1.000

Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **BVV** 

Description: Broken Void Visible

Distance (ft): 216.7
Structural Grade: 5

O&M Grade: 0
Clock Start/From: 1
Clock To: 3

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES



Code: SSS

Description: Surface Spalling


Distance (ft): 221.1
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 8
Clock To: 9

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: TFA


Description: Tap Factory Active

Distance (ft): 238.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:



Code: RFJ

Description: Roots Fine Joint

Distance (ft): 241.4
Structural Grade: 0

O&M Grade: 1

Clock Start/From: 9

Clock To: 12

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: FM

Description: Fracture Multiple

Distance (ft): 246.9
Structural Grade: 4
O&M Grade: 0
Clock Start/From: 8
Clock To: 4
1st Value:
2nd Value:
Value Percent:

Continuous Index: F01
Within 8" of Joint: YES



Code: AMH
Description: Manhole

Distance (ft): 248.5
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-605-026