
## **Profile/Photo Observation Report**



Profile/Photo Observation Report								
Date: Pipe Length (ft P.O.#: Customer:	04/16/2018 ): 59-1 City of Hobart	Weather: Owner: Surveyor: Clean Date:	City of Ho M. Pielac		Pre Clean:	PACP 6.0 No Pre-Cleaning M-605-031-M-605-032		
Street:	Connecticut Street		Flow Contr	ol:	Not Controlled			
City:	Hobart, IN		Year Renev	wed:				
Location:	Light Highway		Tape/Med	ia #:	DEP 59			
Purpose:	<b>Routine Assessment</b>		Dia/Height	::	18"			
Use:	Sanitary		Material:		VCP			
Drain Area:			Lining:					
Category:	NA							
Comment:								
Location Detail	ls:		Direction o	of Survey:	Downstream			
US MH:	M-605-031	DS MH:	M-605-032		Total Length Surveyed (ft):	234.5		
O&M Index:	0.00	O&M Quick:		0000	O&M Rating:	0.00		
Structural Index:	2.62	– Structural Qı	uick:	4137	Structural Rating:	34.00		
Overall Index:	2.62	— Overall Quicl	k:	4137	Overall Rating:	34.00		

	Position	Code	Observation	Video (sec)	Grade
1605	5-031				
	.0	AMH	Manhole	0	NA
Camera Direction	0.	MWL	Water Level	7	NA
	24.6	CC	Crack Circumferential	49	S 1
	51.3	CM	Crack Multiple	168	S 3
	64.1	FM	Fracture Multiple	193	S 4
	65.3	TF	Tap Factory	204	NA
	65.3	CM	Crack Multiple	218	S 3
	68.6	TF	Tap Factory	236	NA
	105.3	TF	Tap Factory	317	NA
	/107.5	TBA	Tap Break-in Active	335	NA
	143.8	TF	Tap Factory	387	NA
	145.5	CM	Crack Multiple	415	S 3
	146.9	TF	Tap Factory	451	NA
	183.3	TBA	Tap Break-in Active	900	NA
	186.1	TFC	Tap Factory Capped	918	NA
	201.5	TF	Tap Factory	948	NA
	202.1	CL	Crack Longitudinal	961	S 2
	208.7	FL(S01)	Fracture Longitudinal	983	S 3
		CL(S02)	Crack Longitudinal	1007	S 2
	219.3	TF	Tap Factory	1026	NA
	/// 228.9	FL(F01)	Fracture Longitudinal	1053	S 3
	/// 228.9	CL(F02)	Crack Longitudinal	1061	S 2
	234.5	AMH	Manhole	1079	NA



Code:	АМН
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-605-031



Code: MWL

Description: **Water Level** 

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

NO

Remarks:



Code: CC

**Crack Circumferential** Description:

Distance (ft): 24.6 Structural Grade: 1 O&M Grade: 0 Clock Start/From: 7 Clock To: 10 1st Value:

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: CM

Description: Crack Multiple

Distance (ft): 51.3
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 11
Clock To: 1

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:

\_



Code: FM

Description: Fracture Multiple

Distance (ft): 64.1
Structural Grade: 4

O&M Grade: 0

Clock Start/From: 9

Clock To: 10

1st Value:

2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: TF

Description: **Tap Factory** 

Distance (ft): 65.3 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 10

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: CM

Description: **Crack Multiple** 

Distance (ft): 65.3 Structural Grade: 3 O&M Grade: 0 Clock Start/From: 10 3 Clock To: 1st Value: 2nd Value:

Continuous Index: Within 8" of Joint:

YES

Remarks:

Value Percent:



Code: **TF** 

Description: Tap Factory

Distance (ft): 68.6
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF** 

Description: Tap Factory

Distance (ft): 105.3
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: TBA

Description: Tap Break-in Active

Distance (ft): 107.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:


1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF** 

Description: Tap Factory

Distance (ft): 143.8
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: CM

Description: Crack Multiple

Distance (ft): 145.5
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 10
Clock To: 2

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TF** 

Description: Tap Factory

Distance (ft): 146.9
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:

o or joint.



Code: TBA

Description: **Tap Break-in Active** 

Distance (ft): 183.3 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 10

Clock To:

1st Value: 5.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



TFC Code:

Description: **Tap Factory Capped** 

Distance (ft): 186.1 Structural Grade: 0 O&M Grade: 0 Clock Start/From: 10

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: **TF** 

Description: Tap Factory

Distance (ft): 201.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: CL


Description: Crack Longitudinal

Distance (ft): 202.1
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 12

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint:

YES

Remarks:



Code: FL

Description: Fracture Longitudinal

Distance (ft): 208.7
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 12

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent:

Continuous Index: **S01**Within 8" of Joint: **YES** 

Remarks:



Code: CL


Description: Crack Longitudinal

Distance (ft): 215.4
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 9

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: **S02** Within 8" of Joint: **YES** 

Remarks:



Code: TF

Description: **Tap Factory** 

Distance (ft): 219.3 Structural Grade: 0 0 O&M Grade: Clock Start/From: 10

Clock To:


1st Value: 4.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: FL

Description: **Fracture Longitudinal** 

Distance (ft): 228.9 Structural Grade: 3 O&M Grade: 0 Clock Start/From: 12

Clock To:

4.000 1st Value:

2nd Value: Value Percent:

Continuous Index: F01 Within 8" of Joint: NO

Remarks:



Code: CL

Description: Crack Longitudinal

Distance (ft): 228.9
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 9

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: F02
Within 8" of Joint: NO

Remarks:



Code: AMH
Description: Manhole

Distance (ft): 234.5
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: M-605-032