## **Profile/Photo Observation Report**



	ioto Observation	•				ROBOTICS	
Date:	04/28/2018	Weather:			Coding:	PACP 6.0	
Pipe Length (ft):		Owner:	City of Hobart		Pre Clean:	No Pre-Cleaning	
P.O.#:	125	Surveyor:	M. Pielacha		PSR:	P-504-001-052	
Customer:	City of Hobart	Clean Date:			Shape:	С	
Street:	Wisconsin Street		Flow Control:		Not Controlled		
City:	Hobart, IN		Year Renewed	•			
Location:	<b>Light Highway</b>		Tape/Media #	:	<b>DEP 125</b>		
Purpose:	Routine Assessme	nt	Dia/Height:		18"		
Use:	Sanitary		Material:		VCP		
Drain Area:			Lining:				
Category:	NA						
Comment:	YES501824 Submit	al 2					
Location Detai	ls:		Direction of Su	ırvey:	Upstream		
US MH:	M-504-001	DS MH:	M-605-052	Total	Length Surveyed (ft	: 134.1	
0&M Index:	2.75	O&M Quick:	3	321	O&M Rating:	11.00	
tructural Index	2.33	Structural Q	2	326	Structural Rating:	21.00	
Overall Index:	2.46	Overall Quic	k: 3	627	Overall Rating:	32.00	

	Position	Code	Observation	Video (sec)	Grade
605-	052				
003	0.0	АМН	Manhole	0	NA
Н	\\.0	MWL	Water Level	10	NA
	6.1	TFC	Tap Factory Capped	28	NA
	11.7	TF	Tap Factory	50	NA
	15.2	ТВ	Tap Break-in	63	NA
	16.2	TBD	Tap Break-in Defective	78	M 3
	16.2	RML	Roots Medium Lateral	85	M 3
ш	32.0	FL	Fracture Longitudinal	117	S 3
Щ	48.8	TF	Tap Factory	146	NA
	50.7	FL	Fracture Longitudinal	162	S 3
	51.7	TF	Tap Factory	174	NA
ш	54.3	CM	Crack Multiple	194	S 3
П	67.5	CL	Crack Longitudinal	221	S 2
Н	76.2	CL(S01)	Crack Longitudinal	243	S 2
щ	82.2	TF	Tap Factory	260	NA
ш	95.1	CL(F01)	Crack Longitudinal	283	S 2
Ш	121.4	CL	Crack Longitudinal	324	S 2
	133.2	TFD	Tap Factory Defective	354	M 2
	133.2	RML	Roots Medium Lateral	362	M 3
ш	134.1	MSA	Abandoned Survey	393	NA
504-					

Code:



Description:	Manhole		
Distance (ft):	.0		
Structural Grade:	0		
O&M Grade:	0		
Clock Start/From:			
Clock To:			
1st Value:			
2nd Value:			
Value Percent:			
Continuous Index:			
Within 8" of Joint:	NO		
Remarks:	M-605-052		

AMH



Code: MWL

Description: Water Level

Distance (ft): .0
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: N

Remarks:

5.000

NO



Code: **TFC** 

Description: Tap Factory Capped

Distance (ft): 6.1
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF** 

Description: Tap Factory

Distance (ft): 11.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: TB

Description: Tap Break-in

Distance (ft): 15.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: TBD

Description: **Tap Break-in Defective** 

Distance (ft): 16.2 Structural Grade: 0 3 O&M Grade: Clock Start/From: 1

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: **Defective** 



Code: **RML** 

Description: **Roots Medium Lateral** 

Distance (ft): 16.2 Structural Grade: 0 O&M Grade: 3 Clock Start/From: 1

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: FL

Description: Fracture Longitudinal


Distance (ft): 32.0
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 1

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TF** 

Description: Tap Factory

Distance (ft): 48.8
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 10

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: FL

Description: Fracture Longitudinal

Distance (ft): 50.7
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 1

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: **TF** 

Description: Tap Factory

Distance (ft): 51.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: CM

Description: Crack Multiple

Distance (ft): 54.3
Structural Grade: 3
O&M Grade: 0
Clock Start/From: 1
Clock To: 3

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: CL

Description: Crack Longitudinal

Distance (ft): 67.5
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 2

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:

leo.



Code: CL

Description: Crack Longitudinal

Distance (ft): 76.2
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: **S01**Within 8" of Joint: **YES** 

Remarks:



Code: **TF** 

Description: Tap Factory

Distance (ft): 82.2
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 2

Clock To:

1st Value: **4.000** 

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: CL

Description: Crack Longitudinal

Distance (ft): 95.1
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: F01
Within 8" of Joint: NO

Remarks:

Code: CL

Description: Crack Longitudinal

Distance (ft): 121.4
Structural Grade: 2
O&M Grade: 0
Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

YES

Remarks:



Code: **TFD** 

Description: **Tap Factory Defective** 

Distance (ft): 133.2 Structural Grade: 0 2 O&M Grade: Clock Start/From: 11

Clock To:

1st Value: 4.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks: **Defective** 



Code: **RML** 

Description: **Roots Medium Lateral** 

Distance (ft): 133.2 Structural Grade: 0 O&M Grade: 3 Clock Start/From: 11

Clock To: 1st Value: 2nd Value:

Value Percent: 30.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 134.1
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO

Remarks: roots