
Profile/Photo Observation Report						
Date: Pipe Length (f	<b>04/16/2018</b>	Weather: Owner:	City of Hobar	Coding: t Pre Clean:	PACP 6.0 No Pre-Cleaning	
P.O.#:	6 <b>4-3</b>	Surveyor:	M. Pielacha	PSR:	M-605-056-M-605-055	
Customer:	City of Hobart	Clean Date:		Shape:	С	
Street:	Beverly Lane		Flow Control:	Not Controlle	d	
City:	Hobart, IN		Year Renewed:			
Location:	Light Highway		Tape/Media #:	DEP 64		
Purpose:	Routine Assessmen	nt	Dia/Height:	15"		
Use:	Sanitary		Material:	СР		
Drain Area:			Lining:			
Category:	NA					
Comment:						
Location Deta	ils:		Direction of Su	rvey: Downstream		
US MH:	M-605-056	DS MH:	M-605-055	Total Length Surveyed (f	t): <b>20.7</b>	
D&M Index:	4.00	O&M Quick:	41	00 O&M Rating:	4.00	
Structural Inde>	<: <b>0.00</b>	 Structural Q	uick: 00	00 Structural Rating	0.00	
Overall Index:	4.00	Overall Quic	k: 41	00 Overall Rating:	4.00	






Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-605-056

Friday, October 1, 2021



Code:	MWL
Description:	Water Level
	•
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code: Description:	LL Alignment Left
Distance (ft):	3.6
Structural Grade:	0
O&M Grade:	4
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	25.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	AMH
Description:	Manhole
Distance (ft):	20.7
Distance (ft):	20.7
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-605-055