Profile/Photo Observation Report



Date: 04/25/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 163.6 Owner: NA Pre Clean: Not Known

P.O.#: Surveyor: **Jen Costello** PSR: **P-605-074-075**Customer: **Clean Date: 01/01/1900** Shape: **C**

Street: MUNICIPAL DR & S ASH ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Light Highway Tape/Media #:

Purpose: Maintenance Related Dia/Height: 12"
Use: Sanitary Material: VCP

Drain Area: NA Lining: Cured in Place

Category: NA

Comment: Flow direction wrong. Root ball in pipe entrance.

Location Details: Direction of Survey: **Downstream**

US MH: M-605-075 DS MH: M-605-074 Total Length Surveyed (ft): .4

3100 3.00 3.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 3.00 3100 3.00 Overall Quick: Overall Rating: Overall Index:

	Position	Code	Observation	Video (sec)	Grade
M(605-)0	75				
	.0	AMH	Manhole	10	NA
	0.	MWL	Water Level	21	NA
-	\\.0	RMJ	Roots Medium Joint	33	M 3
-	.4	MSA	Abandoned Survey	45	NA
Camera Direction					
ı					

Code:



Description:	Manhole	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-605-075	

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: NO

Remarks:

0

Code: RMJ Description: **Roots Medium Joint**

Distance (ft): .0

O&M Grade: 3 Clock Start/From: 6 Clock To: 9

1st Value: 2nd Value:

Value Percent: 30.000

Continuous Index:

Structural Grade:

Within 8" of Joint: YES

Remarks:





Code: MSA

Description: Abandoned Survey

Distance (ft): .4
Structural Grade: 0

O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index:

Within 8" of Joint: NO Remarks: roots