Profile/Photo Observation Penort



Profile/Photo Observation Report								
Date: Pipe Length (ft P.O.#: Customer:	05/07/2018 :): 618 City of Hobart	Weather: Owner: Surveyor: Clean Date:	City of Hoba		Coding: Pre Clean: PSR: Shape:	PACP 6.0 No Pre-Cleaning P-606-002-003 C		
Street: Lake Park Avenue		Flow Control:		Not Controlled				
City:	Hobart, IN		Year Renewe					
Location:	Light Highway		Tape/Media	# :	DEP 618			
Purpose:	Routine Assessment		Dia/Height:		18"			
Use:	Sanitary		Material:		PVC			
Drain Area:			Lining:					
Category:	NA							
Comment:	5-21-2018							
Location Details:		Direction of Survey:		Downstream				
US MH:	M-606-002	DS MH:	M-606-003	То	tal Length Surveyed (ft):	70.3		
0&M Index:	2.00	O&M Quick:	-	2A00	O&M Rating:	28.00		
tructural Index	0.00	— Structural Qւ	uick:	0000	Structural Rating:	0.00		
Overall Index:	2.00	Overall Quicl		2A00	Overall Rating:	28.00		

1 Thursday, May 4, 2023

	Position	Code	Observation	Video (sec)	Grade
606-002					
	0	AMH	Manhole	0	NA
	0	MWL	Water Level	9	NA
\.	5	DSF(S01)	Deposits Settled Fine	29	M 2
7	70.3	DSF(F01)	Deposits Settled Fine	386	M 3
7	70.3	MSA	Abandoned Survey	391	NA



Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-606-003

Thursday, May 4, 2023 2



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0

Clock Start/From:

O&M Grade:

Clock To: 1st Value: 2nd Value:

Value Percent:

Continuous Index:

Within 8" of Joint: NO

15.000

0

Remarks:



Code: **DSF**

Description: **Deposits Settled Fine**

Distance (ft): .5 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 4 Clock To: 8 1st Value:

2nd Value:

Value Percent: 10.000 Continuous Index: **S01** Within 8" of Joint: YES

Remarks:

3 Thursday, May 4, 2023



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 70.3
Structural Grade: 0
O&M Grade: 3
Clock Start/From: 4
Clock To: 8

1st Value: 2nd Value:

Value Percent: 20.000
Continuous Index: F01
Within 8" of Joint: NO

Remarks:



Code: MSA

Description: Abandoned Survey

Distance (ft): 70.3
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO Remarks: debris

Thursday, May 4, 2023 4