


Pipe Length (ft): Owner: City of Hobart Pre Clean: P.O.#: 301 Surveyor: B. Helbling PSR: Customer: City of Hobart Clean Date: Shape: Street: West 8th Street Flow Control: Not Controlled	PACP 6.0 Not Known
	P-606-021-009 C
City Very Penewada	
City: Hobart, IN Year Renewed:	
Location: Light Highway Tape/Media #: DEP301	
Purpose: Routine Assessment Dia/Height: 18"	
Use: Sanitary Material: VCP	
Drain Area: Lining:	
Category: NA	
Comment: 5-21-2018	
Location Details: Direction of Survey: Upstream	
US MH: M-606-009 DS MH: M-606-021 Total Length Surveyed (ft):	242.9
O&M Index: 2.41 O&M Quick: 4233 O&M Rating:	41.00
Structural Index: 3.00 Structural Quick: 4121 Structural Rating:	6.00
Overall Index: 2.47 Overall Quick: 4333 Overall Rating:	47.00

	Position	Code	Observation	Video (sec)	Grade
606-02	1				
	.0	AMH	Manhole	0	NA
	.0	MWL	Water Level	17	NA
	34.9	ID	Infil Dripper	118	M 3
	62.9	DSF	Deposits Settled Fine	342	M 2
	68.7	TF	Tap Factory	548	NA
	77.1	TFA	Tap Factory Active	732	NA
	81.1	DSF(S01)	Deposits Settled Fine	829	M 2
	119.8	DSF(F01)	Deposits Settled Fine	1160	M 2
	167.7	CL	Crack Longitudinal	1292	S 2
	167.7	DAE	Deposits Attached Encrustation	1337	M 2
	169.3	ID	Infil Dripper	1393	M 3
	171.9	FM	Fracture Multiple	1442	S 4
	191.9	DAE	Deposits Attached Encrustation	1677	M 3
	191.9	IR	Infil Runner	1709	M 4
	212.3	DAE	Deposits Attached Encrustation	1786	M 2
	212.3	IR	Infil Runner	1806	M 4
	232.8	DAE	Deposits Attached Encrustation	1873	M 2
	242.9	AMH	Manhole	1931	NA



Code:	АМН
Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-606-009

Thursday, May 4, 2023 2



Code: MWL Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent: 10.000

Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: ID Description: **Infil Dripper**

Distance (ft): 34.9 Structural Grade: 0 O&M Grade: 3 Clock Start/From: 1

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: **DSF**

Description: Deposits Settled Fine

Distance (ft): 62.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 5
Clock To: 7

1st Value: 2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: **TF**

Description: Tap Factory

Distance (ft): 68.7
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 10

Clock To:

1st Value: **6.000**

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:

0 01 301116.

Thursday, May 4, 2023 4



Code: **TFA**

Description: **Tap Factory Active**

Distance (ft): 77.1 Structural Grade: 0 0 O&M Grade: Clock Start/From: 1

Clock To:

1st Value: 6.000

2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: DSF

Description: **Deposits Settled Fine**

Distance (ft): 81.1 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 5 7 Clock To: 1st Value:

Value Percent: 5.000 Continuous Index: **S01** NO

Remarks:

2nd Value:

Within 8" of Joint:



Code: **DSF**

Description: **Deposits Settled Fine**

Distance (ft): 119.8 Structural Grade: 0 2 O&M Grade: Clock Start/From: 5 7 Clock To:

1st Value: 2nd Value:

5.000 Value Percent: Continuous Index: F01 Within 8" of Joint: NO

Remarks:



CL Code:

Description: **Crack Longitudinal**

Distance (ft): 167.7 Structural Grade: 2 O&M Grade: 0 Clock Start/From: 12

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO

Remarks:



Code: DAE

Description: **Deposits Attached Encrustation**

Distance (ft): 167.7 Structural Grade: 0 2 O&M Grade: Clock Start/From: 7 Clock To: 5

1st Value: 2nd Value:

5.000 Value Percent:

Continuous Index:

Within 8" of Joint:

YES

Remarks:



Code: ID

Description: **Infil Dripper**

Distance (ft): 169.3 Structural Grade: 0

O&M Grade: 3 Clock Start/From: 12

Clock To:

1st Value: 2nd Value:

Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: FΜ

Description: **Fracture Multiple**

Distance (ft): 171.9 Structural Grade: 4 O&M Grade: 0 Clock Start/From: 9 Clock To: 3

1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: DAE

Description: **Deposits Attached Encrustation**

Distance (ft): 191.9 Structural Grade: 0 O&M Grade: 3 Clock Start/From: 7 Clock To: 11 1st Value:

2nd Value:

Value Percent: 15.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: IR

Description: **Infil Runner**

Distance (ft): 191.9 Structural Grade: 0 O&M Grade: 4 Clock Start/From: 10

Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: DAE

Description: **Deposits Attached Encrustation**

Distance (ft): 212.3 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 1 5 Clock To: 1st Value:

2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: IR

Description: Infil Runner

Distance (ft): 212.3
Structural Grade: 0
O&M Grade: 4
Clock Start/From: 5

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint:

Remarks:

YES



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 232.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 1
Clock To: 5
1st Value:

2nd Value:

Value Percent: 5.000


Continuous Index:

Within 8" of Joint:

Remarks:

YES

Thursday, May 4, 2023 10



Code: AMH
Description: Manhole

Distance (ft): 242.9
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value: Value Percent:

Continuous Index: Within 8" of Joint:

Remarks: M-606-021

NO