

Profile/Photo Observation Report



Date:	03/12/2024	Weather:		Coding:	PACP 7.0
Pipe Length (ft):	174.0	Owner:	City of Hobart	Pre Clean:	Heavy Cleaning
P.O.#:		Surveyor:	S. Bucklin	PSR:	P-606-053-052
Customer:	City of Hobart	Clean Date:	03/04/2024	Shape:	C

Street:	S ASH ST	Flow Control:	Not Controlled
City:	Hobart, IN	Year Renewed:	
Location:	Local rural streets with light traffic, t	Tape/Media #:	
Purpose:	Sewer System Evaluation Survey (SS	Dia/Height:	12"
Use:	Sanitary Sewage Pipe	Material:	VCP
Drain Area:		Lining:	None
Category:	NA		
Comment:			
Location Details:		Direction of Survey:	Downstream
US MH:	M-606-052	DS MH:	M-606-053
		Total Length Surveyed (ft):	171.8


O&M Index:	2.06	O&M Quick:	322E	O&M Rating:	74.00
Structural Index:	2.54	Structural Quick:	413A	Structural Rating:	66.00
Overall Index:	2.26	Overall Quick:	413A	Overall Rating:	140.00

	Position	Code	Observation	Video (sec)	Grade
		M-606-052			
	.0	AMH	Manhole	0	NA
	.0	MWL	Miscellaneous Water Level	112	NA
	.5	B	Broken	195	S 4
	.5	DAE(S01)	Deposits Attached Encrustation	207	M 2
	2.1	JAM	Joint Angular Medium	293	S 3
	2.1	MWL	Miscellaneous Water Level	309	NA
	9.8	MWLS(S02)	Miscellaneous Water Level Sag	371	S 3
	29.2	MWLS(F02)	Miscellaneous Water Level Sag	492	S 3
	30.2	JAM	Joint Angular Medium	557	S 3
	38.0	MWLS(S03)	Miscellaneous Water Level Sag	607	S 2
	54.0	CM(S04)	Crack Multiple	708	S 3
	55.6	TFD	Tap Factory Defective	753	M 3
	79.6	MWLS(F03)	Miscellaneous Water Level Sag	875	S 2
	79.6	CM(F04)	Crack Multiple	881	S 3
	79.6	MWL	Miscellaneous Water Level	892	NA
	97.4	TFD	Tap Factory Defective	1046	M 3
	110.2	SZ	Surface Damage Other	1113	NA
	111.6	MWLS(S05)	Miscellaneous Water Level Sag	1136	S 2
	113.5	CL	Crack Longitudinal	1168	S 2
133.1	CM	Crack Multiple	1327	S 3	
133.7	MWLS(F05)	Miscellaneous Water Level Sag	1350	S 2	
171.2	DAE(F01)	Deposits Attached Encrustation	1625	M 2	
171.8	AMH	Manhole	1718	NA	
		M-606-053			




Code: **AMH**
Description: **Manhole**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks: **M-606-052**




Code: **MWL**
Description: **Miscellaneous Water Level**

Distance (ft): **.0**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **35.000**
Continuous Index:
Within 8" of Joint: **NO**
Remarks:



Code: **B**
Description: **Broken**

Distance (ft): **.5**
Structural Grade: **4**
O&M Grade: **0**
Clock Start/From: **9**
Clock To: **3**
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks:



Code: **DAE**
Description: **Deposits Attached Encrustation**

Distance (ft): **.5**
Structural Grade: **0**
O&M Grade: **2**
Clock Start/From: **8**
Clock To: **4**
1st Value:
2nd Value:
Value Percent: **5.000**
Continuous Index: **S01**
Within 8" of Joint: **YES**
Remarks:



Code: **JAM**
Description: **Joint Angular Medium**

Distance (ft): **2.1**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks:




Code: **MWL**
Description: **Miscellaneous Water Level**

Distance (ft): **2.1**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **20.000**
Continuous Index:
Within 8" of Joint: **NO**
Remarks:




Code: **MWLS**
Description: **Miscellaneous Water Level Sag**

Distance (ft): **9.8**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **35.000**
Continuous Index: **S02**
Within 8" of Joint: **NO**
Remarks:



Code: **MWLS**
Description: **Miscellaneous Water Level Sag**

Distance (ft): **29.2**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **35.000**
Continuous Index: **F02**
Within 8" of Joint: **NO**
Remarks:



Code: **JAM**
Description: **Joint Angular Medium**

Distance (ft): **30.2**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **NO**
Remarks:




Code: **MWLS**
Description: **Miscellaneous Water Level Sag**

Distance (ft): **38.0**
Structural Grade: **2**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **30.000**
Continuous Index: **S03**
Within 8" of Joint: **NO**
Remarks:



Code: **CM**
Description: **Crack Multiple**

Distance (ft): **54.0**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From: **11**
Clock To: **1**
1st Value:
2nd Value:
Value Percent:
Continuous Index: **S04**
Within 8" of Joint: **YES**
Remarks:



Code: **TFD**
 Description: **Tap Factory Defective**

Distance (ft): **55.6**
 Structural Grade: **0**
 O&M Grade: **3**
 Clock Start/From: **11**
 Clock To:
 1st Value: **6.000**
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks: **TAP CRACKED. SERVICE OFFSET. SOIL VISIBLE. WATER CONSTANTLY RUNN**



Code: **MWLS**
 Description: **Miscellaneous Water Level Sag**

Distance (ft): **79.6**
 Structural Grade: **2**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent: **30.000**
 Continuous Index: **F03**
 Within 8" of Joint: **NO**
 Remarks:




Code: **CM**
 Description: **Crack Multiple**

Distance (ft): **79.6**
 Structural Grade: **3**
 O&M Grade: **0**
 Clock Start/From: **11**
 Clock To: **1**
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index: **F04**
 Within 8" of Joint: **YES**
 Remarks:



Code: **MWL**
 Description: **Miscellaneous Water Level**

Distance (ft): **79.6**
 Structural Grade: **0**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent: **10.000**
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks:



Code: **TFD**
Description: **Tap Factory Defective**

Distance (ft): **97.4**
Structural Grade: **0**
O&M Grade: **3**
Clock Start/From: **11**
Clock To:
1st Value: **6.000**
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks: **ENCrustATION COMING DOWN THE SERVICE AND FROM THE SERVICE TO**




Code: **SZ**
Description: **Surface Damage Other**

Distance (ft): **110.2**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From: **8**
Clock To: **9**
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks: **A PIECE CHIPPED OFF THE JOINT.**




Code: **MWLS**
 Description: **Miscellaneous Water Level Sag**

Distance (ft): **111.6**
 Structural Grade: **2**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent: **20.000**
 Continuous Index: **S05**
 Within 8" of Joint: **NO**
 Remarks:



Code: **CL**
 Description: **Crack Longitudinal**

Distance (ft): **113.5**
 Structural Grade: **2**
 O&M Grade: **0**
 Clock Start/From: **9**
 Clock To:
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **YES**
 Remarks:




Code: **CM**
Description: **Crack Multiple**

Distance (ft): **133.1**
Structural Grade: **3**
O&M Grade: **0**
Clock Start/From: **8**
Clock To: **2**
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within 8" of Joint: **YES**
Remarks:




Code: **MWLS**
Description: **Miscellaneous Water Level Sag**

Distance (ft): **133.7**
Structural Grade: **2**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent: **20.000**
Continuous Index: **F05**
Within 8" of Joint: **NO**
Remarks:



Code: **DAE**
 Description: **Deposits Attached Encrustation**

Distance (ft): **171.2**
 Structural Grade: **0**
 O&M Grade: **2**
 Clock Start/From: **8**
 Clock To: **4**
 1st Value:
 2nd Value:
 Value Percent: **5.000**
 Continuous Index: **F01**
 Within 8" of Joint: **YES**
 Remarks:



Code: **AMH**
 Description: **Manhole**

Distance (ft): **171.8**
 Structural Grade: **0**
 O&M Grade: **0**
 Clock Start/From:
 Clock To:
 1st Value:
 2nd Value:
 Value Percent:
 Continuous Index:
 Within 8" of Joint: **NO**
 Remarks: **M-606-053**