Profile/Ph	oto Observatio	n Report			RedZone
Date:	04/08/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft): 229.6	Owner:	NA	Pre Clean:	No Pre-Cleaning
P.O.#:		Surveyor:	Jen Costello	PSR:	P-606-060-061
Customer:		Clean Date:	01/01/1900	Shape:	C
Street:	FOXCROFT STREE	т	Flow Control:	Not Contro	olled
City:	Hobart, IN		Year Renewed:		
Location:	Yard		Tape/Media #:		
Purpose:	Routine Assessme	ent	Dia/Height:	10"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:	Flow direction is	marked wrong.			
Location Detai	ls:		Direction of Sur	vey: Upstream	
US MH:	M-606-061	DS MH:	M-606-060	Total Length Surveye	d (ft): 8.1
0&M Index:	2.00	O&M Quick:	260	00 O&M Rating:	12.00
structural Index:	4.00	Structural Qu	uick: 410		4.00
Overall Index:	2.29	Overall Quicl	<: 412	26 Overall Ratin	g: 16.00

	Position	Code	Observation	Video (sec)	Grade
M-60	6-060				
	.0	AMH	Manhole	10	NA
	.0	MWL	Water Level	21	NA
	0.	DSF	Deposits Settled Fine	32	M 2
	4.3	TBI	Tap Break-in Intruding	52	M 2
	4.8	FM	Fracture Multiple	65	S 4
	4.8	DAE	Deposits Attached Encrustation	76	M 2
	5.9	TF	Tap Factory	90	NA
	7.1	IW	Infil Weeper	104	M 2
	7.1	DAZ	Deposits Attached Other	115	M 2
5	8.0	TF	Tap Factory	128	NA
ecti	8.0	DAE	Deposits Attached Encrustation	139	M 2
ā	8.1	MSA	Abandoned Survey	150	NA
Camera Direction					
	6-061				




Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-606-060



Code: MWL Description: Water Level


Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	DSF
Description:	Deposits Settled
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	2

Fine

O&M Grade:	2
Clock Start/From:	4
Clock To:	5
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:TBIDescription:Tap Break-in Intruding

Distance (ft):	4.3
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	1
Clock To:	
1st Value:	4.000
2nd Value:	1.000
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	RFL



Code:	FM
Description:	Fracture Multiple
Distance (ft):	4.8
Structural Grade:	4
O&M Grade:	0
Clock Start/From:	1
Clock To:	2
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:DAEDescription:Deposits Attached Encrustation

Distance (ft):	4.8
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	1
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code: Description:	TF Tap Factory
Distance (ft):	5.9
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	10
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	



Code:	IW Infil Weener
Description:	Infil Weeper
Distance (ft):	7.1
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	12
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	


Within 8" of Joint:

Remarks:



Code: Description:	DAZ Deposits Attached Other
Distance (ft):	7.1
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	9
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	

YES



Code:	TF
Description:	Tap Factory

Distance (ft):	8.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	12
Clock To:	
1st Value:	4.000
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	
Remarks:	

and strank		
	AN IN	
		Carlo V

Code:	DAE
Description:	Deposits Attached Encrustation

Distance (ft):	8.0
Structural Grade:	0
O&M Grade:	2
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	10.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:MSADescription:Abandoned Survey

Distance (ft):	8.1
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	DAE