
Profile/Ph	oto Observatio	n Report			RedZon
Date:	04/08/2018	Weather:		Coding:	PACP 6.0
Pipe Length (ft	:): 179.0	Owner:	NA	Pre Clean:	No Pre-Cleaning
P.O.#:		Surveyor:	Jen Costello	PSR:	P-606-075-074
Customer:		Clean Date:	01/01/1900	Shape:	C
Street:	ALLEY BETWEEN	S CONNECTICUT S	T Flow Control:	Not Controlled	ł
City:	Hobart, IN		Year Renewed:		
Location:	Yard		Tape/Media #:		
Purpose:	Routine Assessme	ent	Dia/Height:	12"	
Use:	Sanitary		Material:	VCP	
Drain Area:	NA		Lining:		
Category:	NA				
Comment:					
Location Detai	ls:		Direction of Sur	vey: Upstream	
US MH:	M-606-074	DS MH:	M-606-075	Total Length Surveyed (ft): 6.3
0&M Index:	4.50	O&M Quick:	514	41 O&M Rating:	9.00
tructural Index:	0.00	Structural Q			0.00
Overall Index:	4.50	Overall Quic			9.00





Code: Description:	AMH Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-606-075



Code: MWL Description: Water Level

Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	5.000
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	



Code:	DAE
Description:	Deposits Attached Encrustation

Distance (ft):	6.0
Structural Grade:	0
O&M Grade:	5
Clock Start/From:	8
Clock To:	4
1st Value:	
2nd Value:	
Value Percent:	40.000
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	IR
Description:	Infil Runner

Distance (ft):	6.0
Structural Grade:	0
O&M Grade:	4
Clock Start/From:	12
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	YES
Remarks:	



Code:	
Description:	

MSA	
Abandoned	Survey

Distance (ft):	6.3
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	unknown