Profile/Photo Observation Report



Date: 04/08/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 157.0 Owner: NA Pre Clean: No Pre-Cleaning P.O.#: Surveyor: Jen Costello PSR: P-606-076-075

Customer: Clean Date: 01/01/1900 Shape: C

Street: S CONNECTICUT ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed:
Location: Yard Tape/Media #:

Purpose: Routine Assessment Dia/Height: 12"
Use: Sanitary Material: VCP

Use: Sanitary Material:
Drain Area: NA Lining:

Category: NA

Comment:

Location Details: Direction of Survey: **Upstream**

US MH: M-606-075 DS MH: M-606-076 Total Length Surveyed (ft): 22.8

2.00 2300 6.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Quick: Structural Rating: Structural Index: 2.00 2300 6.00 Overall Index: Overall Rating: Overall Quick:

Position	Code	Observation	Video (sec)	Grade
606-076				
.0	AMH	Manhole	10	NA
0.	MWL	Water Level	21	NA
7.6	DAE(S01)	Deposits Attached Encrustation	48	M 2
22.8	DAE(F01)	Deposits Attached Encrustation	90	M 2
22.8	MSA	Abandoned Survey	101	NA

Code:



Description:	Manhole	
Distance (ft):	.0	
Structural Grade:	0	
O&M Grade:	0	
Clock Start/From:		
Clock To:		
1st Value:		
2nd Value:		
Value Percent:		
Continuous Index:		
Within 8" of Joint:	NO	
Remarks:	M-606-076	

AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0

Clock Start/From:

Clock To: 1st Value: 2nd Value:


Value Percent: 20.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: DAE

Description: **Deposits Attached Encrustation**

Distance (ft): 7.6 Structural Grade: 0 O&M Grade: 2 Clock Start/From: 8 Clock To: 4 1st Value: 2nd Value:

Value Percent: 5.000 Continuous Index: **S01** Within 8" of Joint: YES

Remarks:



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 22.8
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 8
Clock To: 4
1st Value:

2nd Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: YES

Remarks:

Code: MSA

Description: Abandoned Survey



Distance (ft): 22.8
Structural Grade: 0

O&M Grade: **0**

Clock Start/From: Clock To: 1st Value: 2nd Value: Value Percent: Continuous Index:

Within 8" of Joint: NO Remarks: DAE