Profile/Photo Observation Report



Date: 04/07/2018 Weather: Coding: PACP 6.0

Pipe Length (ft): 212.5 Owner: NA Pre Clean: No Pre-Cleaning P.O.#: Surveyor: Mark Ruby PSR: P-606-096-095

Customer: Clean Date: 01/01/1900 Shape: C

Street: ALLEY BETWEEN S WASHINGTON ST Flow Control: Not Controlled

City: Hobart, IN Year Renewed: Location: Yard Tape/Media #:

Purpose: Routine Assessment Dia/Height: 10"
Use: Sanitary Material: VCP

Drain Area: NA Lining:

Category: NA

Comment: P_C unknown obstruction, flow direction is marked wrong.

Location Details: Direction of Survey: **Downstream**

US MH: M-606-095 DS MH: M-606-096 Total Length Surveyed (ft): 125.2

2.12 512C 53.00 O&M Index: O&M Quick: O&M Rating: 0.00 0000 0.00 Structural Rating: Structural Index: Structural Quick: 2.12 512C 53.00 Overall Quick: Overall Rating: Overall Index:

.0 .0 .0 .5.2	AMH MWL	Manhole	10	NA
.0			10	NA
	MWL	147 1 1		
5.2		Water Level	21	NA
	DAE	Deposits Attached Encrustation	43	M 2
8.9	DAE(S01)	Deposits Attached Encrustation	62	M 2
42.6	TF	Tap Factory	141	NA
44.5	TF	Tap Factory	158	NA
/66.5	TF	Tap Factory	214	NA
72.4	TF	Tap Factory	237	NA
123.9	DAE(F01)	Deposits Attached Encrustation	352	M 2
125.2	RBB	Roots Ball Barrel	367	M 5
125.2	MSA	Abandoned Survey	378	NA

Code:



Description:	Manhole
Distance (ft):	.0
Structural Grade:	0
O&M Grade:	0
Clock Start/From:	
Clock To:	
1st Value:	
2nd Value:	
Value Percent:	
Continuous Index:	
Within 8" of Joint:	NO
Remarks:	M-606-095

 AMH



Code: MWL

Description: **Water Level**

Distance (ft): .0 Structural Grade: 0 O&M Grade: 0 Clock Start/From:

Clock To: 1st Value: 2nd Value:

Value Percent:


Continuous Index:

Within 8" of Joint:

Remarks:

10.000

NO



Code: DAE

Description: **Deposits Attached Encrustation**

5.2 Distance (ft): Structural Grade: 0 O&M Grade: 2 Clock Start/From: 7 Clock To: 12 1st Value:


2nd Value:

Value Percent: 5.000

Continuous Index:

Within 8" of Joint: YES

Remarks:



Code: DAE

Description: Deposits Attached Encrustation

Distance (ft): 8.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:

2nd Value:

Value Percent: 5.000
Continuous Index: S01
Within 8" of Joint: YES

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 42.6
Structural Grade: 0

O&M Grade: 0


Clock Start/From: 1

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 44.5
Structural Grade: 0
O&M Grade: 0
Clock Start/From: 12

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 66.5
Structural Grade: 0

O&M Grade: 0


Clock Start/From: 12

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: **TF**

Description: Tap Factory

Distance (ft): 72.4
Structural Grade: 0

O&M Grade: 0

Clock Start/From: 3

Clock To:

1st Value: **4.000**

2nd Value: Value Percent: Continuous Index: Within 8" of Joint:

Remarks:



Code: DAE


Description: Deposits Attached Encrustation

Distance (ft): 123.9
Structural Grade: 0
O&M Grade: 2
Clock Start/From: 7
Clock To: 5
1st Value:

Value Percent: 5.000
Continuous Index: F01
Within 8" of Joint: YES

Remarks:

2nd Value:



Code: RBB

Description: Roots Ball Barrel

Distance (ft): 125.2
Structural Grade: 0
O&M Grade: 5
Clock Start/From: 12
Clock To: 12

1st Value: 2nd Value:


Value Percent: 90.000

Continuous Index:

Within 8" of Joint:

Remarks:

NO



Code: MSA

Description: Abandoned Survey

Distance (ft): 125.2
Structural Grade: 0
O&M Grade: 0

Clock Start/From:

Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:

Within 8" of Joint: NO Remarks: RBB